



Arizona Nuclear Power Project

P.O. BOX 52034 • PHOENIX, ARIZONA 85072-2034

RECEIVED
NRC

1986 SEP 29 AM 11:18

September 24, 1986
ANPP-38392-WEI/LAS/DRL-92.11

REGION V WIRE

U. S. Nuclear Regulatory Commission
Region V
1450 Maria Lane - Suite 210
Walnut Creek, CA 94596-5368

Attention: Mr. D. F. Kirsch, Acting Director
Division of Reactor Safety and Projects
Palo Verde Nuclear Generating Station (PVNGS)
Units 2, 3
Docket Nos. 50/530

Subject: Time Extension For Report - DER 86-20
A 50.55(e) Potentially Reportable Deficiency Relating to
Damper Seals Not Meeting Required Specifications.
File: 86-006-216; D.4.33.2

Reference: (A) Telephone Conversation between R. C. Sorenson and
D. R. Larkin on June 3, 1986. (Initial Notification -
DER 86-20)
(B) ANPP-37195, dated July 2, 1986. (Interim Report -
DER 86-20)

Dear Sir:

The NRC was notified of a potentially reportable deficiency in reference (A) and an interim report was issued by reference (B). At that time it was estimated that a final report would be available by September 26, 1986.

As a result of vendor testing, additional investigations and evaluations of the transportability and root cause are needed. It is now expected that this information will be finalized by October 17, 1986 at which time a complete report will be submitted.

Very truly yours,

J. G. Haynes
Vice President
Nuclear Production

JGH/DRL:kp

cc: See Page 2

8610160003 860924
PDR ADOCK 05000530
S PDR

IE-27 .10

ANPP-38392-WEI/LAS/DRL-92.11
September 24, 1986
DER 86-20 - Time Extension
Mr. D. F. Kirsch
Acting Director
Page Two

cc: J. M. Taylor
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

A. C. Gehr (4141)
R. P. Zimmerman (6295)

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway - Suite 1500
Atlanta, Georgia 30339