

Appendix A

NOTICE OF VIOLATION

The Curators of the University of
Missouri

Docket No. 50-186

Based on the inspection conducted on May 24-26, 1978, it appears that certain of your activities were in noncompliance with NRC requirements, as noted below. Items 1 and 2 are infractions, and item 3 is a deficiency.

1. Contrary to 10 CFR 73.60(b) and Section III, Part 1, A(4)(b) of the University of Missouri - Columbia Physical Security Plan, the licensee does not search each individual before exiting from the fuel vault which is a material access area.
2. Contrary to Section III (A)(b) of the University of Missouri - Columbia Security Plan, a RIII inspector gained unauthorized access to the [REDACTED] by entering through the freight door which was open at the time for the loading of freight.
3. Contrary to 10 CFR 73.50(C)(7), the key and lock to the truck door which provides access to the vital area is not changed upon termination of employment of any employee who had access to such.

8-74-78-131
Copy 6 of 6 copies
Pages

THIS DOCUMENT IS NOT TO BE
REPRODUCED WITHOUT SPECIFIC
APPROVAL OF RIII

Page 5 of 11