

October 23, 1986

RECO Industries, Incorporated
ATTN: Mr. Stuart Point
President
Box 25189
Richmond, Virginia 23260

Gentlemen:

Thank you for your letter dated October 9, 1986, which further described the corrective action RECO has implemented in response to our request for additional information. The corrective action and preventive measures appear adequate to assure that weld rod auxiliary storage oven temperatures are checked daily.

The corrective action described in your response will be reviewed during a future NRC inspection.

Sincerely,

Original signed by
Robert F. Heishman

Robert F. Heishman, Chief
Vendor Program Branch
Division of Quality Assurance, Vendor
and Technical Training Center Programs
Office of Inspection and Enforcement

DISTRIBUTION:

- DMB:IE:09 ✓
- VPB Reading
- DQAVT Reading
- RStarostecki
- JPartlow
- BGrimes
- HMiller
- RHeishman
- JCraig
- JStone
- LParker
- AGrella
- RØdegaarden, NMSS
- TJohnson, NMSS
- RCilimberg
- KCLeu
- CAbbate

See previous coverwork

VPB:DQAVT	SC/VPB:DQAVT	BC/VPB:DQAVT
CAbbate:tt	JCraig	RHeishman
10/ /86	10/ /86	10/ /86