

DMB COPY

OCT 22 1986

Gremmer-Bablitch, Consulting  
Engineers  
ATTN: Jim Feigleson, Chief  
Executive Officer  
1007 Ellis St.  
Stevens Point, WI 54481

License No. 48-20289-01

Gentlemen:

This refers to the routine safety inspection conducted by Mr. G. L. Shear of this office on September 24, 1986, of activities authorized by NRC Byproduct Material License No. 48-20289-01 and to the discussion of our findings with you and members of your staff at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

The responses directed by this letter and the accompanying Notice (Order) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

D. J. Sreniawski, Chief  
Nuclear Materials Safety  
Section 2

8610280235 861022  
REG3 LIC30  
48-20289-01 PDR

Enclosure: Notice of  
Violation

cc w/enclosure:  
DCS/RSB (RIDS)

IE07  
||

RIII *yes*  
6 10/8/86  
Shear/md

*yes*  
RIII  
*yes*  
Sreniawski  
10/10