



**TU**ELECTRIC

Log # TXX-6523  
File # 10110  
903.9  
Ref # 10CFR50.55(e)

William G. Council  
Executive Vice President

June 19, 1987

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)  
BUCKET NOS. 50-445 AND 50-446  
AIR ACCUMULATORS FOR CONTROL VALVES  
SDAR: CP-87-15 (INTERIM REPORT)

Gentlemen:

On May 20, 1987, we verbally notified your Mr. I. Barnes of a deficiency involving the air accumulators for air operated control valves. This is an interim report of a potentially reportable item under the provisions of 10CFR50.55(e).

Specifically, 22 air accumulators for air operated control valves have been reviewed as a result of installation deficiencies and the lack of removal of desiccant from the accumulator tanks. The installation documents for these accumulators have not been located. Several accumulators in both Units 1 & 2 have been found to contain desiccant although the installations were completed. Also, nonconformance reports have been issued to document these conditions.

Our evaluation of these conditions is scheduled to be completed by July 15, 1987.

Our next report on this issue will be submitted no later than August 22, 1987.

Very truly yours,

W. G. Council

MCP/d1

c - R. D. Martin, Region IV  
Resident Inspectors, CPSES (3)

8706250427 870619  
PDR ADOCK 05000445  
S PDR

IE27  
1/0