

MAY 11 1987

Dr. Zinovy Reytblatt
Associate Professor
Department of Mathematics
Illinois Institute of Technology
Chicago, Illinois 60616

Dear Dr. Reytblatt:

This letter responds to your letter of February 20, 1987, and its attachments. The Chairman has referred your technical concerns to the Commission's staff to determine if you have raised new or different issues not previously considered in response to your earlier requests. The staff has completed its review of the subject letter and concludes that you have not raised any new or different issues and that the issues identified in your letter of February 20, 1987, and its attachments, have been considered in response to your earlier requests.

One item in your February 20, 1987 letter and its attachments, was described as a "newly discovered" description of a Zion Leak Rate Computer program. You identified this description, Attachment R to PT-PC-101, as a page from a typical Commonwealth Edison computer program description. It states that, should the number of temperature sensors in a containment subvolume become equal to zero (due to sensor failures), the temperature of the next higher number subvolume will be used for the temperature of that subvolume. The NRC has previously reviewed the issue of inoperable temperature sensors and determined that if there are no functional temperature sensors in a subvolume, then the average temperature of an adjoining subvolume may be used. The Zion plant uses subvolumes that are numbered such that consecutive subvolumes are adjacent to each other. Therefore, this issue is not new and has been previously considered by the staff.

Sincerely,

Original signed by
Thomas E. Murley

Thomas E. Murley, Director
Office of Nuclear Reactor Regulation

DISTRIBUTION

Docket File
NRC & L PDR
PSB Rdg
EDO Rdg
TMurley
OGC-JGoldberg
Massburg ~~OGC~~ (EDO-002745)
JCraig
JKudrick
Davis, R:III
M. Bridges - 2745

Green Ticket File
JPulsipher
ATHadani
LShao
JRichardson
VStello
JTaylor
TRehm
Beckjord, RES
Murray, OGC
Grimsley, ARM

OGC-H
C. Mullins

*See previous white for concurrences.

PSB:DEST	PSB:DEST	PSB:DEST	OGC-Beth	AD:DEST	D:DEST	DD:NRR	O:NRR
JPulsipher;cf*	JKudrick*	JCraig*	CMullins	ATHadani*	LShao*	JSwezek	TMurley
4/30/87	5/1/87	5/1/87	5/4/87	5/1/87	5/4/87	5/1/87	5/10/87

By telephone
to J. Pulsipher, w/ changes
5/4/87

PS
5/6/87

8705130270 870511
PDR ADOCK 05000295
P PDR

Dr. Zinovy Reytblatt
Associate Professor
Department of Mathematics
Illinois Institute of Technology
Chicago, Illinois 60616

Dear Dr. Reytblatt:

This letter responds to your letter of February 20, 1987. The Chairman has referred your technical concerns to the Commission's staff to determine if you have raised new or different issues not previously considered in response to your earlier requests. The staff has completed its review of the subject letter and concludes that you have not raised any new or different issues and that the issues identified in your letter of February 20, 1987, have been considered in response to your earlier requests.

One item in your February 20, 1987 letter was described as a "newly discovered" description of a Zion Leak Rate Computer program. You identified this description, Attachment R to RT-PC-101, as a page from a typical Commonwealth Edison computer program description. It states that, should the number of temperature sensors in a containment subvolume become equal to zero (due to sensor failures), the temperature of the next higher number subvolume will be used for the temperature of that subvolume. The NRC has previously reviewed the issue of inoperable temperature sensors and determined that if there are no functional temperature sensors in a subvolume, then the average temperature of an adjoining subvolume may be used. The Zion plant uses subvolumes that are numbered such that consecutive subvolumes are adjacent to each other. Therefore, this issue is not new and has been previously considered by the staff.

Sincerely,

Thomas E. Murley, Director
Office of Nuclear Reactor Regulation

DISTRIBUTION

Docket File	Green Ticket File
NRC & L PDR	JPulsipher
PSB Rdg	ATHadani
EDO Rdg	LShao
TMurley	JRichardson
OGC-JGoldberg	VStello
PPAS (EDO-002745)	JTaylor
JCraig	TRehm
JKudrick	Beckjord, RES
Davis, R:III	Murray, OGC
	Grimsley, ARM

PSB:DEST
JPulsipher;cf
4/30/87

PSB:DEST
JKudrick
5/1/87

PSB:DEST
JCraig
5/1/87

OGC-Beth
C. Mullins
5/4/87

AD:DEST
ATHadani
5/1/87

D:DEST
LShao
5/4/87

DD:NRR
JSniezek
5/1/87

D:NRR
TMurley
5/1/87

By telephone
to J. Pulsipher
5/4/87, 12:03 PM,
w/ changes noted.

Dr. Zinovy Reytblatt
Associate Professor
Department of Mathematics
Illinois Institute of Technology
Chicago, Illinois 60616

Dear Dr. Reytblatt:

This letter responds to your letter of February 20, 1987. The Chairman has referred your technical concerns to the Commission's staff to determine if you have raised new or different issues not previously considered in response to your earlier requests. The staff has completed its review of the subject letter and concludes that you have not raised any new or different issues and that the issues identified in your letter of February 20, 1987 have been considered in response to your earlier requests.

One item in your February 20, 1987 letter was described as a "newly discovered" description of a Zion Leak Rate Computer program. You identified this description, Attachment R to PT-PC-101, as a page from a typical Commonwealth Edison computer program description. It states that, should the number of temperature sensors in a containment subvolume become equal to zero (due to sensor failures), the temperature of the next higher number subvolume will be used for the temperature of that subvolume. The NRC has previously reviewed the issue of inoperable temperature sensors and determined that if there are no functional temperature sensors in a subvolume, then the average temperature of an adjoining subvolume may be used. The Zion plant uses subvolumes that are numbered such that consecutive subvolumes are adjacent to each other. Therefore, this issue is not new and has been previously considered by the staff.

Sincerely,

Thomas E. Murley, Director
Office of Nuclear Reactor Regulation

DISTRIBUTION

Docket File

NRC & L PDR

PSB Rdg

EDO Rdg

TMurley

OGC-JGoldberg

PPAS (EDO-002745)

JCraig

JKudrick

Davis, R:III

Green Ticket File

JPulsipher

ATHadani

LShao

JRichardson

VStello

JTaylor

TRehm

Beckjord, RES

Murray, OGC

Grimsley, ARM

PSB:DEST
JPulsipher;cf
4/30/87

[Signature]
PSB:DEST
JKudrick
4/1/87

[Signature]
PSB:DEST
JCraig
5/1/87

OGC-Beth
5/ /87

[Signature]
AD:DEST
ATHadani
5/ /87

[Signature]
D:DEST
LShao
5/4/87

DD:NRR
JSniezek
5/ /87

D:NRR
TMurley
5/ /87

MAY 11 1987

Dr. Zinovy Reytblatt
Associate Professor
Department of Mathematics
Illinois Institute of Technology
Chicago, Illinois 60616

Dear Dr. Reytblatt:

This letter responds to your letter of February 20, 1987, and its attachments. The Chairman has referred your technical concerns to the Commission's staff to determine if you have raised new or different issues not previously considered in response to your earlier requests. The staff has completed its review of the subject letter and concludes that you have not raised any new or different issues and that the issues identified in your letter of February 20, 1987, and its attachments, have been considered in response to your earlier requests.

One item in your February 20, 1987 letter and its attachments, was described as a "newly discovered" description of a Zion Leak Rate Computer program. You identified this description, Attachment R to PT-PC-101, as a page from a typical Commonwealth Edison computer program description. It states that, should the number of temperature sensors in a containment subvolume become equal to zero (due to sensor failures), the temperature of the next higher number subvolume will be used for the temperature of that subvolume. The NRC has previously reviewed the issue of inoperable temperature sensors and determined that if there are no functional temperature sensors in a subvolume, then the average temperature of an adjoining subvolume may be used. The Zion plant uses subvolumes that are numbered such that consecutive subvolumes are adjacent to each other. Therefore, this issue is not new and has been previously considered by the staff.

Sincerely,

Original signed by
Thomas E. Murley

Thomas E. Murley, Director
Office of Nuclear Reactor Regulation

DISTRIBUTION

Docket File

NRC & L PDR

PSB Rdg

EDO Rdg

TMurley

OGC-JGoldberg

Massburg ~~OGC~~ (EDO-002745)

JCraig

JKudrick

Davis, R:III

M. Anderson - 2745

Green Ticket File

JPulsipher

ATHadani

LShao

JRichardson

VStello

JTaylor

TRehm

Beckjord, RES

Murray, OGC

Grimsley, ARM

*See previous white for concurrences.

PSB:DEST
JPulsipher;cf*
4/30/87

PSB:DEST
JKudrick*
5/1/87

PSB:DEST
JCraig*
5/1/87

OGC-Beth
CMullins
5/4/87

AD:DEST
ATHadani*
5/1/87

D:DEST
LShao*
5/4/87

DO:NR
JStezek
5/1/87

O:NR
TMurley
5/10/87

*By telephone
to J. Pulsipher, w/ changes
5/14/87*

*PS
5/16/87*

MAY 11 1987

Dr. Zinovy Reytblatt
Associate Professor
Department of Mathematics
Illinois Institute of Technology
Chicago, Illinois 60616

Dear Dr. Reytblatt:

This letter responds to your letter of February 20, 1987, and its attachments. The Chairman has referred your technical concerns to the Commission's staff to determine if you have raised new or different issues not previously considered in response to your earlier requests. The staff has completed its review of the subject letter and concludes that you have not raised any new or different issues and that the issues identified in your letter of February 20, 1987, and its attachments, have been considered in response to your earlier requests.

One item in your February 20, 1987 letter and its attachments, was described as a "newly discovered" description of a Zion Leak Rate Computer program. You identified this description, Attachment R to PT-PC-101, as a page from a typical Commonwealth Edison computer program description. It states that, should the number of temperature sensors in a containment subvolume become equal to zero (due to sensor failures), the temperature of the next higher number subvolume will be used for the temperature of that subvolume. The NRC has previously reviewed the issue of inoperable temperature sensors and determined that if there are no functional temperature sensors in a subvolume, then the average temperature of an adjoining subvolume may be used. The Zion plant uses subvolumes that are numbered such that consecutive subvolumes are adjacent to each other. Therefore, this issue is not new and has been previously considered by the staff.

Sincerely,

Original signed by
Thomas E. Murley

Thomas E. Murley, Director
Office of Nuclear Reactor Regulation

DISTRIBUTION

Locket File

NRC & L PDR

PSB Rdg

EDO Rdg

TMurley

OGC-JGoldberg

Massburg ~~OGC~~ (EDO-002745)

JCraig

JKudrick

Davis, R:III

M. Bridges - 2745

Green Ticket File

JPulsipher

ATHadani

LShao

JRichardson

VStello

JTaylor

TRehm

Beckjord, RES

Murray, OGC

Grimsley, ARM

*See previous white for concurrences.

PSB:DEST
JPulsipher;cf*
4/30/87

PSB:DEST
JKudrick*
5/1/87

PSB:DEST
JCraig*
5/1/87

OGC-Beth
CMullins
5/4/87

AD:DEST
ATHadani*
5/1/87

D:DEST
LShao*
5/4/87

DO: NRR
JStezek
5/1/87

O: NRR
TMurley
5/10/87

*By telephone
to J. Pulsipher, w/ changes
5/14/87*

*PS
5/6/87*