



An Illinova Company

Illinois Power Company  
P.O. Box 678  
Clinton, IL 61727  
Tel 217 935-8881 x3900  
Fax 217 935-4632

John P. McElwain  
Chief Nuclear Officer

U-603172

2C.220

September 13, 1999

Docket No. 50-461

10CFR50.73

Document Control Desk  
Nuclear Regulatory Commission  
Washington, D.C. 20555


Subject: Clinton Power Station - Unit 1  
Licensee Event Report No. 1996-010-01

Dear Madam or Sir:

Enclosed is Licensee Event Report (LER) No. 1996-010-01: Plant Shutdown Due to Unidentified Reactor Coolant System Leakage from Degraded Reactor Recirculation Pump Seal Greater Than Technical Specification Limit. This report has been revised to include the cause of the event, corrective action, and discussion of similar events. Other changes have been made to add, correct, or clarify event details. This report is being submitted in accordance with the requirements of 10CFR50.73.

The enclosed report contains a commitment to replace the existing reactor recirculation pump seal design with an improved design.

Sincerely yours,

  
John P. McElwain  
Chief Nuclear Officer

RSF/krk

Enclosure

cc: NRC Clinton Licensing Project Manager  
NRC Resident Office, V-690  
Regional Administrator, Region III, USNRC  
Illinois Department of Nuclear Safety  
INPO Records Center

9909200103 990913  
PDR ADOCK 05000461  
S PDR

JE221