



Entergy Operations, Inc.  
P.O. Box B  
Killona, LA 70066  
Tel 504 739 6242

Early C. Ewing, III  
Director  
Nuclear Safety & Regulatory Affairs  
Waterford 3

W3F1-98-0050  
A4.05  
PR

April 1, 1998

U S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D.C. 20555

Subject: Waterford 3 SES  
Docket No. 50-382  
License No. NPF-38  
Reporting of Licensee Event Report

Gentlemen:

Attached is Licensee Event Report (LER) 98-003-00 for Waterford Steam Electric Station Unit 3. This report provides details of both Hydrogen Analyzers being inoperable due to undersized thermal overloads. This condition is being reported pursuant to 10CFR50.73(a)(2)(i)(B) and 10CFR50.36(c)(2) as a condition prohibited by Technical Specifications.

Very truly yours,

E.C. Ewing  
Director,  
Nuclear Safety & Regulatory Affairs

ECE/GCS/ssf  
Attachment

cc: E.W. Merschoff (NRC Region IV), C.P. Patel (NRC-NRR),  
A.L. Garibaldi, J.T. Wheelock - INPO Records Center,  
J. Smith, N.S. Reynolds, NRC Resident Inspectors Office,  
Administrator - LRPD

9804070257 980401  
PDR ADOCK 05000382  
S PDR

11/  
JE22