

APPENDIX A

NOTICE OF VIOLATION

Public Service Company of Colorado
Fort St. Vrain

Docket: 50-267
License: DPR-34

During an NRC inspection conducted on August 1-31, 1987, a violation of NRC requirements was identified. The violation involved inadequate procedures for control of radioactivity. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1987), the violation is listed below:

Inadequate Procedures for Control of Radioactivity

Technical Specification AC 7.4.a.1 requires that procedures shall be established, implemented, and maintained covering the activities recommended in Appendix A of Regulatory Guide 1.33, November 1972. paragraph G of Appendix A to Regulatory Guide 1.33 delineates procedures for the control of radioactivity.

Contrary to the above, no procedures existed on August 20, 1987, to establish responsibility or provide directions for actions to be taken to control contamination if an individual attempts to exit the protected area after the portal monitor alarms.

This is a Severity Level IV violation. (Supplement IV) (267/8721-01)

Pursuant to the provisions of 10 CFR 2.201, Public Service Company of Colorado is hereby required to submit a written statement or explanation to this Office within 30 days of the date of the letter transmitting this Notice. This reply, should include for each violation: (1) the reason for the violation if admitted, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.

Dated at Arlington, Texas,
this 14th day of September 1987

8709180270 870914
PDR ADOCK 05000267
Q PDR