

RIVER BEND STATION

POST OFFICE BOX 220 ST FRANCISVILLE LOUISIANA 70775

AREA CODE 504 635-6094 346-8651

June 30, 1987 RBG-26189 File Nos. G9.5, G15.4.1

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

Gentlemen:

River Bend Station - Unit 1 Refer to: Region IV Docket No. 50-458/Report 85-31

This response supplements Gulf States Utilities Company's (GSU) letter dated September 2, 1985, concerning the Notice of Violation contained in NRC Inspection Report No. 50-458/85-31.

GSU had previously committed to revise surveillance test procedures (STP) by December 31, 1986 to incorporate changes made to the Integrated Leak Rate Test (ILRT) procedure 1-PT-57-1.

The next performance of this STP is scheduled during the second refueling outage, therefore GSU is scheduling completion of this commitment by December 31, 1987.

Sincerely,

J. E. Booker

J. E. Booky

Manager-River Bend Oversight River Bend Nuclear Group

JEB/RJK/AJK/RRS/es

cc: Mr. Robert D. Martin, Regional Administrator U. S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1000 Arlington, TX 76011

NRC Resident Inspector P. O. Box 1051 St. Francisville, LA 70775