Docket No.: 030-13337 License No.: 53-17797-01

Control No.: 70527

Kuakini Medical Center 347 North Kuakini Street Honolulu, Hawaii 96817

Attention: Mr. Masaichi Tasaka

President

Gentlemen:

Enclosed is the NRC license amendment which you originally requested in your letter dated October 17, 1986, and which we discussed in our letters to you dated November 12, 1987 and December 2, 1986, copies enclosed. Please note that only the Amersham Model AMC.26 source was approved for use in the Osteomap analyzer.

Please review the enclosed document carefully and be sure that you understand all conditions. If there are any errors or questions, please notify us so that we can provide appropriate corrections and answers.

Any future correspondence relating to your license should specifically reference your license and docket numbers to expedite your inquiry.

Sincerely,

Beth A. Riedlinger Health Physicist (Licensing) Nuclear Materials Safety Section

Enclosure: Attachment A

Amendment No. 16 to License No. 53-17797-01 Letters dated November 12, 1987 and 12/2/86

8707160538 870312 REG5 LIC30 53-17797-01 PDR

OFFICE	RV Riedlinger	fr				
DATE !	3/12/87			******************		
	318 (10/80) NRCM		OFFICIAL	PECORD C	OPV	₩ U.S. GPO 1983-400-2-

INCOMING CALL RESON CALLING Enid Deneau RESON CALLED BLECT Kuakini (av	OFFICE/ADDRESS SIEMENS OFFICE/ADDRESS	PHONE NUMBER EXTENSION (3/2) 635-3396 PHONE NUMBER EXTENSION
Enid Deneau	Siemens :	(312) 635-3396
RSON CALLED	THE RESIDENCE OF THE PARTY OF THE PROPERTY OF THE PARTY O	THE THE PART OF THE PARTY OF TH
*	OFFICE/ADDRESS	PHONE NUMBER EXTENSION
BJECT Kunkini (av		
BLECT KURRINI (av		
Kunkini lav	CONVERSATION	
Muster of the	eproved "Osteo Map" unit	53-17797-01
MMARY	,	
		, -1 // , , ,
The registry	sheet has been issued	for the Osteo Map
Unit FDA	approval was granted	on Feb. 2 1987
nou.	70	
Plano resus	rect Control No. 7047	74 22.1
		1 une
process am	endment request.	
	U	
tepplained to	hat no action can be take	Pen until a
1 041	Octor Man Marite short	:- frad
copy of the	Osteo Map registry street	15 /4/44
to us.		
V	£	
	- 2	S. a. Rudlinger
		gir
	2 2	
ERREDTO: Frances	-	M ADVISE ME OF
ION REQUESTED		ACTION TAKEN.
use this as the	"incoming" and pull ug	D INITIALS TOWN
Control No. 704	INITIALS BAR	
condition	DATE 2/20/87	
ION TAKEN	INITIALS	
	(m' + of 57017+	
	V126/87	0.4%
		1 114 7 8
	1/2010/	DATE
DRM 218 (4-76)	Mesmole?	DATE

DEC 2 1986

Docket No.: 030-13337 License No.: 53-17797-01

Control No.: 70474

Kuakini Medical Center 347 North Kuakini Street Honolulu, Hawaii 96817

Attention: Mr. Masaichi Tasaka

President

Gentlemen:

Enclosed is the NRC license amendment which you requested.

Please review the enclosed document carefully and be sure that you understand all conditions. If there are any errors or questions, please notify us so that we can provide appropriate corrections and answers.

It should be noted that the Osteo Map device was not added to your license at this time, as discussed in my letter to you dated November 12, 1986, copy enclosed. Once the manufacturer notifies you that the source and device registry sheets have been issued, you may resubmit your request and refer to Control No. 70474.

Any future correspondence relating to your license should specifically reference your license and docket numbers to expedite your inquiry.

Sincerely,

Beth A. Riedlinger

*Health Physicist (Licensing)

Nuclear Materials Safety Section

Enclosure: Attachment A

Amendment No. 14 to License No. 53-17797-01

Letter dated November 12, 1986

RV BC Riedlinger:fr 12/2/86

Docket No.: 030-13337 License No.: 53-17797-01 Control No.: 70474

Kuakini Medical Center 347 North Kuakini Street Honolulu, Hawaii 96817

Attention: Mr. Masaichi Tasaka

President

Gentlemen:

This is in reference to your request dated October 17, 1986 for amendment of your byproduct material license. In order to complete our review, we need the following additional information:

- 1. Our Headquarters staff is currently reviewing the 200 millicurie americium 241 source and the Osteo Map device which you described in your letter of October 17, 1986. We cannot add the source or device to your license until their review is complete. You may wish to withdraw this portion of your request and resubmit it at a later date. Refer to Control No. 70474 when you resubmit.
- 2. You should submit the procedure mentioned in 5.B. of Item 18-1, "Waste Disposal Procedures", which was attached to your letter dated October 17, 1986. Also, describe the counting equipment and the criteria used to determine whether test tubes may be disposed to normal trash.

We will continue the review of your amendment request upon receipt of this information. In order to continue prompt review of your application, we request that you submit your response to this letter within 30 calendar days from the date of this letter. Please reply in duplicate, and refer to Mail Control No. 70474.

Sincerely,

8704270148 Lp.

Beth A. Riedlinger Health Physicist (Licensing) Nuclear Materials Safety Section

CEP							COLUMN COLUMN COLUMN COLUMN
MED	Riedlinger:	fr		***************************************		***************************************	****************
re þ	11//2/86			***************************************		705	27
MRC	318 (10/80) NRCM	0240	OFFICIAL	DECODE	The same of the sa		000 1083m400.2