



Log # TXX-89111
File # 10110
903.9
Ref. # 10CFR50.55(e)

March 1, 1989

W. J. Cahill
Executive Vice President

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NOS. 50-445 AND 50-446
CABLE TRAY TEE FITTINGS
SDAR: CP-85-50 (SUPPLEMENT REPORT)

Gentlemen:

On September 30, 1987, TU Electric letter logged TXX-6771 provided notification of a deficiency involving the use of improper welding processes in the manufacturing of cable tray tee fittings. The latest report on this issue was TXX-88808, dated November 30, 1988. This report is submitted to update the status of the corrective actions for Unit 1.

The engineering evaluation discussed in TXX-88808 is continuing and has identified the need for field modifications. Completion of the engineering evaluation and associated field modifications is scheduled for May 30, 1989. The completion schedule for Unit 2 has not changed.

Sincerely,

William J. Cahill, Jr.

RSB/ddm

c - Mr. R. D. Martin, Region IV
Resident Inspectors, CPSES (3)

8903070180 890301
PDR ADOCK 05000445
S PNU

IE27
1/0