USNRC-DS 1987 OCT 19 A 10: 18

Docket No. 50-282 Docket No. 50-306

Northern States Power Company ATTN: Mr. C. E. Larson Vice President, Nuclear Generation 414 Nicollet Mall Minneapolis, MN 55401

Gentlemen:

This refers to the routine safety inspection conducted by Mr. J. H. Neisler of this office on August 31 through September 24, 1987, of activities at Prairie Island, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-42 and No. DPR-60 and to the discussion of our findings with Mr. E. Watzl and other members of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

8710190257 871009 PDR ADDCK 05000282 Q PDR Original Signed By J. 1. Marrison

J. J. Harrison, Chief Engineering Branch

Enclosure: Inspection Reports No. 50-282/87015(DRS); No. 50-306/87014(DRS)

See Attached Distribution

RIII Neisler/lms RIII RMS Gardner Harrison 10/9/81 RTIL DLS for Jackin Booto

150

Distribution

cc w/enclosure:
E. L. Watzl, Plant Manager
DCD/DCB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII Prairie
Island
Resident Inspector, RIII Monticello
John W. Ferman, Ph.D.,
Nuclear Engineer, MPCA
State Liaison Officer, State
of Minnesota