



A Centenor Energy Company

DONALD C. SHELTON  
Vice President - Nuclear  
(419) 249-2300

Docket Number 50-346

License Number NPF-3

Serial Number 1643

March 15, 1989

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

Subject: Davis-Besse Nuclear Power Station Fifth Refueling Outage ASME  
Section XI Inservice Inspection Summary Report

Gentlemen:

Enclosed is a copy of the ASME Section XI Summary Report and Owner's Data Report (Form NIS-1) for the March 1988 to December 1988 inservice inspection performed at the Davis-Besse Nuclear Power Station, Unit No. 1 during the fifth refueling outage. This report is submitted in accordance with the ASME Boiler and Pressure Vessel Code, Section XI, Article IWA-6000, "Records and Reports", Section IWA-6220. The data supporting this Summary Report is on file at the Davis-Besse site and is available for review.

If you have any questions concerning this matter, please contact Mr. R. W. Schrauder, Nuclear Licensing Manager, at (419) 249-2366.

Very truly yours,

GBK/dlm

Enclosure

cc: P. M. Byron, DB-1 NRC Resident Inspector  
A. B. Davis, Regional Administrator, NRC Region III  
T. V. Wambach, DB-1 NRC Senior Project Manager  
State of Ohio

8903220213 890315  
PDR ADOCK 05000346  
PDC

A047  
11

Docket Number 50-346  
License Number NPF-3  
Serial Number 1643  
Enclosure 1

ASME SECTION XI SUMMARY REPORT FOR TOLEDO EDISON  
DAVIS-BESSE NUCLEAR POWER STATION UNIT NO. 1  
FIFTH REFUELING OUTAGE