



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

July 24, 1987

Director of Nuclear Reactor Regulation
U S Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555


PRAIRIE ISLAND NUCLEAR GENERATING PLANT
DOCKET NOS. 50-282 LICENSE NOS. DPR-42
50-306 DPR-60

Unit 1 Inservice Inspection Summary Report
Refueling Outage Number 11

Attached for your review are four copies of the report, "Inservice Inspection - Examination Summary, April 7, 1987 to May 14, 1987, Refueling Outage Number 11, Inspection Period 1, Second Interval." This report is a summary of the examinations performed during the last 1987 refueling outage of Prairie Island Unit No. 1.

This report identifies the components examined, the examination methods used, and the examination number for inspections conducted during the refueling outage which was concluded on May 14, 1987. A summary of the inspection results is also provided.

This report is being submitted in accordance with the Prairie Island ASME Code Section XI Inservice Inspection and Testing Program. As noted in that Program, submittal of the attached summary report is intended to satisfy the inspection reporting requirements contained in IWA-6220 of Section XI of the ASME Boiler and Pressure Vessel Code.


David Musolf
Manager Nuclear Support Services

- c: Regional Administrator - III, NRC (2 copies of attachment)
NRR Project Manager, NRC (1 copy of attachment)
Resident Inspector, NRC (w/o attachment)
G Charnoff (w/o attachment)
H Baron, Chief Boiler Inspector, State of MN (1 copy of attachment)
S Tack, Hartford Insurance (1 copy of attachment)

Attachment

8708030117 870724
PDR ADDCK 05000282
Q PDR

A047
11