

APPENDIX A
NOTICE OF VIOLATION

Robert J. Carlin and Associates
875 Route 9
South Amboy, New Jersey 08879

Docket No. 030-19015
License No. 29-19641-01

As a result of the inspection conducted on September 8, 1987, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violation was identified:

- A. Condition 13(1) of License No. 29-19641-01 requires that sealed sources containing byproduct material be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to the above, sealed sources containing 10 millicuries of cesium-137 and 40 millicuries of americium-241 were not tested for leakage from December 1985 to August 1986 and November 1986 to September 1987, intervals of more than six months.

This is a Severity Level IV violation. (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, Robert J. Carlin and Associates is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including; (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8711040328 871103
REG1 LIC30
29-19641-01 PDR