



PECO NUCLEAR

A Unit of PECO Energy

Michael P. Gallagher, P.E.
Plant Manager
Limerick Generating Station

PECO Energy Company
Limerick Generating Station
PO Box 2300
Sanatoga, PA 19464-0920
610 718 2000

July 2, 1998

Docket No. 50-352
License No. NPF-39

U.S. Nuclear Regulatory Commission
Attn.: Document Control Desk
Washington, DC 20555

SUBJECT: Licensee Event Report
Limerick Generating Station - Unit 2

This LER concerns the discovery of three Barksdale Model C9622-3-B differential pressure switches located on the Main Turbine Relayed Emergency Trip System that were determined to be inoperable from a common cause. These switches provide input to the Reactor Recirculation Pump End-of-Cycle Trip and Reactor Protection System. This condition resulted in two or more independent trains of a single safety system being inoperable due to a common cause.

Reference:	Docket No. 50-352
Report Number:	2-98-001
Revision Number:	00
Event Date:	June 2, 1998
Report Date:	July 2, 1998
Facility:	Limerick Generating Station P.O. Box 2300, Sanatoga, PA 19464

This LER is being submitted pursuant to the requirements of 10CFR50.73(a)(2)(vii).

Very truly yours,

MCK

cc: H. J. Miller, Administrator Region I, USNRC
A. L. Burritt, USNRC Senior Resident Inspector, LGS

9807070397 980702
PDR ADOCK 05000353
S PDR

41
JL 22