

DMB COPY

NOV 13 1987

30-29372

Howard Laboratories, Inc.  
ATTN: David L. Howard, Ph.D.  
P. O. Box 369  
Dayton, OH 45449

License No. 34-16876-02

Gentlemen:

This refers to the routine safety inspection conducted by Ms. T. L. Simmons of this office on October 26, 1987, of activities authorized by NRC Byproduct Material License No. 34-16876-02 and to the discussion of our findings with you at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

D. G. Wiedeman, Chief  
Nuclear Materials Safety  
Section 1

Enclosure: Notice of  
Violation

cc w/enclosure:  
DCD/DCB (RIDS)

RIII

RIII

Simmons/abl

Wiedeman

8711160250 B71113  
REG3 LIC30  
34-16876-02 PDR

IED7  
11