NRC FORM 591 PART 1 (8-1997)		U.S. NUCLEAR REGULA	TORY COMMISSI
CFR 2.201	SAFETY AND COM	PLIANCE INSPECTION	
	OAI ETT AITD COM	THE RESIDENCE OF THE PROPERTY	MANAGE HITADY INCOMPRESSOR SAME
Deportment of Ver	torons Affair	2. REGIONAL OFFICE	
Deportment of Veterans Affairs Medical Contex		REGION IV	
Prescotl, AZ		US NUCLEAR REGULATORY COMMISSION 611 RYAN PLAZA DR STE 400 ARLINGTON TX 76011-8064	
EPORT NUMBER(S) 98-0	THE RESIDENCE OF THE PROPERTY OF A SECURITY OF THE PERSON		
030 - 01210	4 LICENSE NUMBER(S)	6-01 5 DATE(S) OF INSPECTION 1998	
egulatory Commission (NRC) rules	and regulations and the conditions of you	ense as they relate to radiation safety and to compliance wour license. The inspection consisted of selective examinate inspector. The inspection findings are as follows:	ith the Nuclear ations of procedure
	findings, no violations were identified.		
non-repetitive, and corrediscretion, were satisfied 35.50(b)(l)	octive action was or is being taken, and the non-cited violation(s) was 35.35(g) 35.32(b)		REG-1600, to exerc
This form is a NOTICE	OF VIOLATION, which is required to be	ow and/or attached, were in violation of NRC requirements posted in accordance with 10 CFR 19.11.	
Contrary to 10	CFR 35,14(b), the	licensee did not notify NRC	WITHIN
30 days after	the authorized user	and radiation safety offices	(R56)
98072101 PDR ADO C	98 980529 OCK 03001210 PDR		
tions is made in accordance with the	e actions described by the to the Inspect ne requirements of 10 CFR 2.201 (corre-	DRRECTIVE ACTIONS tor will be taken to correct the violations identified. This state of the sta	atement of correcti ken, date when full
TITLE	PRINTED NAME		DATE
ICENSEE	Michael J. TRYN	JOSKY Michael & Jynos	5/29/98
IPC INSPECTOR	David D Stor	V Samuel	5/20/00