

~~SAFEGUARDS INFORMATION~~

U.S. NUCLEAR REGULATORY COMMISSION

Report No. 50-346/87032(DRSS)

Docket No. 50-346

License No. NPF-3

Licensee: Toledo Edison Company
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Facility Name: Davis-Besse Nuclear Power Station

Type of Inspection: Enforcement Conference

Enforcement Conference at: NRC Region III Office, Glen Ellyn, Illinois

Date of Enforcement Conference: November 19, 1987

Inspector:

G. L. Pirtle
Physical Security Inspector

11/30/87

Date

Reviewed By:

J. R. Creed
J. R. Creed, Chief
Safeguards Section

11/30/87

Date

Approved By:

B. S. Mallett
B. S. Mallett, Ph.D., Chief
Nuclear Materials Safety
and Safeguards Branch

11/30/87

Date

Inspection Summary

Enforcement Conference on November 19, 1987 (Report No. 50-346/87032(DRSS))
Areas Discussed: Included a review and discussion of circumstances that resulted in a potential violation of the licensee's security plan relating to inadequate penetration resistance for a portion of a vital area barrier. Corrective actions implemented were reviewed and enforcement options were briefly discussed.

8712080053 871201
PDR ADOCK 05000316
PDR
Q

~~SAFEGUARDS INFORMATION~~

Enclosure contains
SAFEGUARDS INFORMATION
Upon separation of this
page is Decontrolled