

Gary R. Peterson Vice President

Duke Energy Corporation

Catawba Nuclear Station 4800 Concord Poad York, SC 29745 (803) 831-4251 OFFICE (803) 831-3426 FAX

August 5, 1998

U. S. Nuclear Regulatory Commission ATTENTION: Document Control Desk Washington, DC 20555-0001

SUBJECT: Duke Energy Corporation

Catawba Nuclear Station Unit 1

Docket No. 50-413

Licensee Event Report 413/98-012

Attached please find Licensee Event Report 413/98-012 entitled Technical Specification 3.0.3 Entry due to Inoperability of Both Trains of Control Room Ventilation caused by Improper System Isolation. The only commitments identified in this report are those listed under the planned corrective actions section.

Questions regarding this Licensee Event Report should be directed to J. W. Glenn at (803) 831-3051.

Velluso R. Peterson

Attachment

Sipsere

100005

9808110090 980805 PDR ADOCK 05000413 TEDD!

U.S. Nuclear Regulatory Commission June 11, 1998 Page 2

XC:

L. A. Reyes
U. S. Nuclear Regulatory Commission
Regional Administrator, Region II
Atlanta Federal Center
61 Forsyth St., SW, Suite 23T85
Atlanta, GA 30303

P. S. Tam NRC Senior Project Manager (CNS) U. S. Nuclear Regulatory Commission Mail Stop 0-14H25 Washington, DC 20555-0001

D. J. Roberts
Senior Resident Inspector (CNS)
U. S. Nuclear Regulatory Commission
Catawba Nuclear Site