



Davis-Besse Nuclear Power Station  
5501 North State Route 2  
Oak Harbor, Ohio 43449-9760

John K. Wood  
Vice President - Nuclear

419-249-2300  
Fax: 419-321-8337

Docket Number 50-346

License Number NPF-3

Serial Number 2555

August 21, 1998

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

Subject: Inservice Inspection Summary Report of the Eleventh Refueling Outage Activities  
Davis-Besse Nuclear Power Station - Unit 1

Ladies and Gentlemen:

In accordance with the 1986 Edition of the American Society of Mechanical Engineers (ASME) Boiler and Pressure Vessel Code Section XI, IWA-6000, enclosed is the subject report covering inservice inspection activities, and repairs and replacements completed through the end of the Davis-Besse Nuclear Power Station, Unit 1 eleventh refueling outage.

Should you have any questions concerning this response, please contact Mr. James L. Freels, Manager - Regulatory Affairs, at (419) 321-8466.

Very truly yours,

CAK/asc

Enclosure

cc: A. G. Hansen, NRC Project Manager  
A. B. Beach, Regional Administrator, NRC Region III  
S. J. Campbell, DB-1 NRC Senior Resident Inspector  
Factory Mutual Engineering Associates (2)  
Ohio Department of Industrial Relations  
Utility Radiological Safety Board

9808310135 980821  
PDR ADOCK 05000346  
G PDR

11  
A047