

APPENDIX

NOTICE OF VIOLATION

Century Geophysical Corporation  
Tulsa, Oklahoma

Docket: 30-11376  
License: 35-04017-04

During an NRC inspection conducted on July 20, 1987, violations of NRC requirements were identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1987), the violations are listed below:

1. License Condition 10 requires that licensed material be stored at 7517 East Pine, Tulsa, Oklahoma, and at 3010 South Energy Lane, Casper, Wyoming, and may be used at temporary job sites.

Contrary to this requirement, the NRC inspector identified that the licensee had established and used, for a period of at least 4 months, a permanent storage site at the residence of one of its employees in Dewer, Oklahoma.

This is a Severity Level IV violation. (Supplement VI)

2. License Condition 19 requires that the licensee shall conduct its program in accordance with the statements, representations, and procedures contained in the license application dated June 8, 1981, and subsequent, referenced documents.

Appendix B, Figure 2 of the operating procedures submitted with the license application requires that radiation surveys, to detect contamination at the borehole, be performed and recorded before and after operations.

Contrary to this requirement, the NRC inspector identified during a demonstration of the performance of this survey that the individual being inspected had been performing and recording a survey of the transportation vehicle rather than performing and recording a survey at the borehole.

This is a Severity Level IV violation. (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, Century Geophysical Corporation is hereby required to submit a written statement or explanation to this Office within 30 days of the date of the letter transmitting this Notice. This reply, should include for each violation: (1) the reason for the violation if admitted, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.

Dated at Arlington, Texas,  
this 11<sup>th</sup> day of September 1987

bcc:

DMB - Original (IE-07)

RD Martin

RL Bangart

WL Fisher

\*D Weiss, RM/ALF (AR-2015)

\*Inspector

\*NMIS

\*MIS System

\*RIV Files (2)

\*RSTS Operator

DA Powers

TM Kernon

\*w/766

20-08M00  
PC & A 11 02 1991

USNRC-DS

1987 SEP 14 A 9 39