

DMB COPY

APR 11 1989

Testmaster Inspection Company, Inc.
ATTN: Wendell B. Cart
P.O. Box 31
Perrysburgh, OH 43551

License No. 34-24872-01

Gentlemen:

This refers to the routine safety inspection conducted by Mr. J. R. Mullauer of this office on March 27 and 28, 1989 of activities authorized by NRC Byproduct Material License No. 34-24872-01 and to the discussion of our findings with you at the conclusion of the inspection.


The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.


Sincerely,




D. G. Wiedeman, Chief
Nuclear Materials Safety
Section 1

Enclosure: Notice of Violation

cc w/enclosure:
DCD/DCB (RIDS)

RIII 
Mullauer/mnj

RIII 
Wiedeman

4/11/89

1207
11

8904190325 890411
REG3 LIC30
34-24872-01 PDC