




- NOTES:
1. REF. CE 006 E-4370-ZIC-130
 2. ALL PIPING DOWNSTREAM OF FIRST & SECOND VALVES ON PIP. HAS 3-EQUIPMENT, IS SEISMIC CATEGORY II.
 3. SHUT DOWN ALL PROCESS & INSTRUMENT LINES CONTAINING RADIOACTIVE SOLUTION THAT HAVE OUTSIDE EXPOSURE.
 4. ALL PIPING & EQUIPMENT VENT & DRAIN VALVES INSIDE PROCESS LINE SEISMIC CATEGORY I BOUNDARY SHALL BE SEISMIC CATEGORY II & SHALL BE LOCKED CLOSED.
 5. DELETED
 6. STANDARD BY WELDING 'C' OF HORIZONTAL RUN MUST BE AT LEAST 18" ABOVE BOTTOM OF TANK.
 7. 'A' CORRESPONDS TO UPPER MOTOR BEARING, 'B' CORRESPONDS TO LOWER MOTOR BEARING.
 8. THE FOLLOWING ICM'S ARE OUTSTANDING AND NOT IN COMPLIANCE IN REVISION 25.
ICM# DCP#
1341 574
9. EMCA, EMPC SPARED

30	AS BUILT FOR 1970	100	100
26	AS BUILT FOR 1970	100	100
22	AS BUILT FOR 1970	100	100
21	AS BUILT FOR 1970	100	100
20	AS BUILT FOR 1970	100	100

ARRANGED FOR LIGHT & DARK
APPROXIMATELY 1/2" X 1/2"

IRC

50-368

8301280359

