Docket No. 50-458

Gulf States Utilities ATTN: Mr. James C. Deddens Senior Vice President (RBNG) Post Office Box 220 St. Francisville, Louisiana 70775

Dear Mr. Deddens:

SUBJECT: CRACK INDICATION IN THE INLET FEEDWATER NOZZLE (N4-A) TO SAFE END WELD - RIVER BEND STATION (TAC NO. 73115)

The NRC staff has reviewed your May 15 and 19, 1989 submittals regarding the circumferential crack flaw found in the Inconel 182 butter area of the Inconel weldment between the N4-A feedwater nozzle and carbon steel safe end. This flaw was found during your 1989 refueling outage. Based on our review of your flaw evaluation, we conclude that River Bend Station, Unit 1 can be safely operated for one additional 18-month fuel cycle in its present configuration pending satisfactory results of the mid-cycle ultrasonic examination of the flawed weld. We request that the results of the mid-cycle ultrasonic examination be submitted to NRC for review prior to plant start-up from the mid-cycle outage to ensure that the structural integrity of the weldment is maintained.

The staff's Safety Evaluation is enclosed as discussed in our May 23, 1989 letter. The reporting and/or recordkeeping requirements contained in this letter affect fewer than ten respondents; therefore, DMB clearance is not required under P.L. 96-511.

Sincerely.

15/

Walter A. Paulson, Project Manager Project Directorate - IV Division of Reactor Projects III. IV, V and Special Projects Office of Nuclear Reactor Regulation

Enclosure: Safety Evaluation

cc w/enclosure: See next page

[RB CRACK INDICATIONS] PD4/LA DAT

PNoonan 06/10/89 PD4/PM WPau Nson: cs 06/14/89

DISTRIBUTION: Ducket File

L. Rubenstein C. Y. Cheng G. Holahan

06/15/89

FHebdon

NEC PDR Local PDR f. Hebdon P. Noonan E. Jordan OGC-Rockville

W. Paulson B. Grimes ACRS(10) PD4 Plant File

PD4 Reading

OFOI

8906210078 890615 ADDCK 05000458 PNU



## UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

June 15, 1989

Docket Wo. 50-458

Gulf States Utilities

ATTN: Mr. James C. Deddens

Senior Vice President (RBNG)

Post Office Box 220

St. Francisville, Louisiana 70775

Dear Mr. Deddens:

SUBJECT: CRACK INDICATION IN THE INLET FEEDWATER NOZZLE (N4-A) TO SAFE END

WELD - RIVER BEND STATION (TAC NO. 73115)

The MPC staff has reviewed your May 15 and 19, 1989 submittals regarding the circumferential crack flaw found in the Inconel 182 butter area of the Inconel weldment between the N4-A feedwater nozzle and carbon steel safe end. This flaw was found during your 1989 refueling outage. Based on our review of your flaw evaluation, we conclude that River Bend Station, Unit 1 can be safely operated for one additional 18-month fuel cycle in its present configuration pending satisfactory results of the mid-cycle ultrasonic examination of the flawed weld. We request that the results of the mid-cycle ultrasonic examination be submitted to NRC for review prior to plant start-up from the mid-cycle outage to ensure that the structural integrity of the weldment is maintained.

The staff's Safety Evaluation is enclosed as discussed in our May 23, 1989 letter. The reporting and/or recordkeeping requirements contained in this letter affect fewer than ten respondents; therefore, OMB clearance is not required under P.L. 96-511.

Sincerely.

Walter A. Pau'son, Project Manager

Project Directorate - IV

Walter A. Paulson

Division of Reactor Projects III, IV. V and Special Projects

Office of Nuclear Reactor Regulation

Enclosure: Safety Evaluation

cc w/enclosure: See next page Mr. James C. Deddens Gulf States Utilities Company

cc: Troy B. Conner, Jr., Esq. Conner and Wetterhahn 1747 Pennsylvania Avenue, NW Washington, D.C. 20006

Mr. Les England
Director - Nuclear Licensing
Gulf States Utilities Company
P. O. Box 220
St. Francisville, LA 70775

Richard M. Troy, Jr., Esq. Assistant Attorney General in Charge State of Louisiana Department of Justice 234 Loyola Avenue New Orleans, Louisiana 70112

Resident Inspector
P. O. Box 1051
St. Francisville, Louisiana 70775

Gretchen R. Rothschild-Reinike Louisianians for Safe Energy, Inc. 2108 Broadway Street New Orleans, Louisiana 70118-5462

Regional Administrator, Region IV U.S. Nuclear Regulatory Commission Office of Executive Director for Operations 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Philip G. Harris Cajun Electric Power Coop. Inc. 10719 Airline Highway P. O. Box 15540 Baton Rouge, LA 70895 River Bend Nuclear Plant

Mr. J. E. Booker Manager-River Bend Oversight P. O. Box 2951 Beaumont, TX 77704

Mr. William H. Spell, Administrator Nuclear Energy Division Office of Environmental Affairs P. O. Box 14690 Baton Rouge, Louisiana 70898

Mr. J. David McNeill, III William G. Davis, Esq. Department of Justice Attorney General's Office 7434 Perkins Road Baton Rouge, Louisiana 70808

H. Anne Plettinger 3456 Villa Rose Drive Baton Rouge, Louisiana 70806

President of West Feliciana Police Jury P. O. Box 1921 St. Francisville, Louisiana 70775

Mr. Frank J. Uddo Uddo & Porter 6305 Elysian Fields Avenue Suite 400 New Orleans, Louisiana 70122