

26 JUN 1987

Docket No. 040-08837

License No. SUB-1428

Teledyne Engineering Services
ATTN: Mr. Donald Messinger, Quality Assurance
and Inspection Supervisor, RSO
130 Second Avenue
Waltham, MA 02254

Gentlemen:

Subject: Inspection No. 040-08837-86-01

This refers to your letter dated February 27, 1987 in response to our letter dated September 9, 1986.

Thank you for informing us of the corrective and preventive actions documented in your letter.

In reference to a telephone conversation with Mr. Malonson on April 13, 1987, we understand that you will clean the area in which the buffing wheel is contained. Based upon the results of appropriate radiation survey measurements, you will dispose of the material removed as either normal or radioactive waste. The radiation survey results shall be maintained in accordance with 10 CFR 20.401(b) to verify compliance with 10 CFR 20.201(b).

If our understanding of this matter is not correct, please advise us in writing within 30 days of the date on this letter.

These actions will be examined during a future inspection of your licensed program.

No reply to this letter is required. Your cooperation with us in this matter is appreciated.

Sincerely,

Original Signed By:
Laurence F. Friedman, Ph.D.

John R. White, Chief
Nuclear Materials Safety Section C
Division of Radiation Safety
and Safeguards

8707010161 870626
REG1 LIC40 PDR
SUB-1428

cc:
Public Document Room (PDR)
Nuclear Safety Information Center (NSIC)
Commonwealth of Massachusetts

"OFFICIAL RECORD COPY"

RETURN ORIGINAL TO
REGION I

11 IE:07

26 JUN 1987

bcc:
Region I Docket Room (w/concurrences)

RI:DRSS
Oberg/mk

6/18/87

RI:DRSS

for White

6/23/87