Mr. Wade Green
Institute of Nuclear Power Operations
Suite 1500, 1100 Circle 75 Parkway
Atlanta, Georgia 30339-3064

Dear Mr. Green:

Enclosed for your information is our biweekly listing of generic communications being considered or under development by the NRC staff. These include Bulletins (type coded BL on the list), Information Notices (IN) and Generic Letters (GL). Temporary Instructions, that cover the special NRC inspection effort resulting from certain generic communications, are listed with the type code TI. This listing includes all proposed generic communications that had been reported to us by August 1, 1989.

Prasad Kadambi

0/

Carl H. Berlinger, Chief Generic Communications Branch Division of Operational Events Assessment Office of Nuclear Reactor Regulation

Enclosure: As stated

DISTRIBUTION w/enclosure: All NRC Division Directors All NRC Branch Chiefs CERossi, NRR CHBerlinger, NRR OGCB Members JOThoma, NRR RFraley, ACRS JLieberman, OE PDR Central Files DCB DOEA R/F OGCB R/F DKirkpatrick R/F SRichardson, DOE RBarber, DOE

OGCB: DOEA: NRR DCKirkpatrick 08/2/892CK C/OGCB: DOEA: NRR CHBerlinger 08/2/89 DF03

RD-25

Page No. 08/02/89

August 3, 1989

PROPOSED GENERIC COMMUNICATIONS
IN PREPARATION WITHIN THE NRC

Enclosure

	ORIGIN. OFFICE	SUBJECT	CONTACT	PHONE	ISSUE DATE
	RVIB	ENVIRONMENTAL QUALIFICATION OF LIMITORQUE MOV ACTUATOR TERMINAL BLOCKS & MARATHON 1600 TERMINAL BLOCKS	ATEXANDER		
IN	CICE	ERRORS IN CALIBRATION OF LEAD/LAG AND RATE CIRCUITS IN REACTOR PROTECTION SYSTEMS.	Joe Joyce	(301) 492-3265	10/31/89
GL	NRR/DOEA OGCB	CHANGE IN FORMAT FOR NRC GENERIC COMMUNICATIONS		(301) 492-1169	10/01/89
GL	NRR/DEST EMEB		Shou-Nien Hou	(301) 492-0904	09/15/89
GL	AEOD	LICENSEE COMMITMENTS FOR EMERGENCY RESPONSE DATA SYSTEM (ERDS) IMPLEMENTATION	John Jolicoeur	(301) 492-4155	08/18/89
GL	NRR/DEST ESGB	NRR RECOMMENDATION ON ISI OF MARK I & II STEEL CONTAINMENTS, REFUELING CAVITIES & ASSOC DRAINAGE SYS	Chen P. Tan	(301) 492-0829	12/31/89
GL	NRR/DEST SELB	RESOLUTION OF GENERIC ISSUE B-56, DIESEL RELIABILITY	Chopia		
GL	NRR/DOEA OTSB	LINE ITEM TECHNICAL SPECIFICATION IMPROVEMENT - REMOVAL OF COMPONENT LISTS	Tom Dunning	(301) 492-1169	10/01/89
GL	NRR/DEST ESGB	MINIMUM EDGE DISTANCE FOR INSTALLATION OF ANCHORS IN CONCRETE	John Ma	(301) 492-1376	10/31/89
11	AEOD	THE REPORTING OF SAFETY VALVE AND SAFETY-RELIEF VALVE EVENTS FURSUANT TO 10 CFR 50.73	Mary S. Wegner	(301) 492-7818	09/01/89
GI	RES/IEB	RESOLUTION OF: GI/70, PORV AND BLOCK VALVE RELIABILITY, AND GI/94, ADDITIONAL LOW TEMP OVERPRESS PROTECTION FOR LWRS	R Kirkwood E Throm	492-3928 -3911	3 09/01/89
Т	I NRR/DES' EMEB	INSPECTION OF IMPLEMENTATION UF GENERIC LETTER TO EXTEND IEB 85-03 "MOV COMMON MODE FAILURES DURING PLANT	Ted Sullivan	(301) 492-090	11/01/89

TRANSIENTS

PROPOSED GENERIC COMMUNICATIONS IN PREPARATION WITHIN THE NRC

TP	ORIGIN. OFFICE	SUBJECT	CONTACT	PHONE	ISSUE DATE
TI		INSPECTION OF COMPLIANCE WITH BULLETIN 88-04: "SAFETY-RELATED FUMP LOSS"	Mike McCoy	(301) 492-0880	11/30/89
GL		REMOVAL OF 3.25 LIMITATION OF SPEC 4.0.2 FOR REFUELING SURVEILLANCES	Tom Dunning	(301) 492-1189	09/01/89
IN		FAILURE OF LIMITORQUE VALVE OPERATOR HOUSINGS	John Harrison	(312) 790-5635	08/03/89
IN	NRR/DOEA OGCB	OPERATING EXPERIENCE FEEDBACK	Vernon Hodge	(301) 492-1169	08/14/89
IN			S. V. Athavale		08/31/89
GL	NRR/DEST SPLB	CONTROL ROOM HABITABILITY SYSTEMS	Charles Nichols	(301) 492-0854	12/31/89
IN		DIESEL GENERATOR FUEL DIL	Vernon Hodge		11/28/89
GL	NRR/DOEA OTSB	LINE-ITEM TECH SPEC IMPROVEMENT - ALT REQUIREMENTS FOR FUEL ASSEMBLIES IN DESIGN FEATURE SECTION OF TECH SPECS	Tom Dunning	(301) 492-1189	09/15/89
GL		ACCIDENT MANAGEMENT STRATEGIES FOR CONSIDERATION IN IPE PROCESS - 10 CFR 50.54	R. Palla	(301) 492-1076	10/15/89
BL	NRR/DEST ECEB	EVALUATION OF HAZARDS ASSOCIATED WITH HYDROGEN, NITROGEN AND PROPANE USED IN NUCLEAR POWER PLANTS	Frank J. Witt	(301) 492-0823	08/15/89
IN	REG V	INGERSOLL-RAND AIR START MOTORS USED ON DIESEL GERERATORS	Don Kirkpatrick		
GL	ECEB	GUIDANCE ON TEMPORARY REPAIR OF SERVICE WATER SYSTEM COMPONENTS	Frank J. Witt	(301) 492-0823	12/31/89
IN	NRR/DRIS RSIB	INADEQUATE FOST MODIFICATION TESTING	S. V. Athavale	(301) 492-0974	08/31/89
IN	NRR/DRIS RSIB	INADEQUATE CONTROL OF TEMPORARY MODIFICATIONS ON SAFETY RELATED SYSTEMS	S. V. Athavale	(301) 492-0974	09/09/89

PROPOSED GENERIC COMMUNICATIONS IN PREPARATION WITHIN THE NRC

	DRIGIN. DFFICE	SUBJECT	CONTACT		1SSUE DATE
BL		GROUNDS IN DIRECT CURRENT DISTRIBUTION SYSTEMS	F. Burrows	(301) 492-0833	10/01/89
	II	REPOSITIONING OF INTERMEDIATE RANGE NEUTRON DETECTORS CAUSED IMPROPER HIGH-FLUX TRIP SETPOINTS		(404) 331-5554	
IN	NRR/CP	POTENTIAL INOPERABILITY OF BORG-WARNER PRESSURE SEAL BONNET CHECK VALVES			
		FIRE INDUCED SPURIOUS ISOLATION SIGNALS			
IN	REGION I	CNEW] LOSS OF RESIDUAL HEAT REMOVAL AT SALEM UNIT 1 DUE TO ACCUMULATOR NITROGEN INJECTION	Prochnow		
		ENEW] UNEXPECTED HIGH RADIATION AREAS RESULTING FROM SPENT FUEL POOL ACTIVITIES			
IN		[NEW] FOTENTIAL CONTRIBUTERS TO INCREASED FIRE RISK			
	NRR/DOEA DEAB	[NEW] DEGRADED GRID VOLTAGE	J. Carter	(301) 492-1194	