

PO. BOX 408 • WISCASSET, MAINE 04578 • (207) 882-6321

August 4, 1989 MN-89-102

GDW-89-253

UNITED STATES NUCLEAR REGULATORY COMMISSION Attention: Document Control Desk Washington, D. C. 20555

References: (a) License No. DPR-36 (Docket No. 50-309)

(b) NRC Bulletin No. 88-10: Non-Conforming Molded-Case Circuit Breakers, dated November 22, 1988

(c) NRC Information Notice No. 88-46: Licensee Report of Defective Molded-Case Circuit Breakers; dated July 8, 1988

(d) NUMARC Letter to USNRC Board of Directors, dated March 9, 1989, IE Bulletin 88-10

(e) MYAPCo Letter to USNRC, dated March 31, 1989 (MN-89-44) (f) MYAPCo Letter to USNRC, dated June 19, 1989 (MN-89-83)

Subject: IE Bulletin No. 88-10, Non-Conforming Molded-Case Circuit Breakers-Completion of Vendor Audits

Gentlemen:

With Maine Yankee's supplemental response to IE Bulletin No. 88-10, Reference (f), Maine Yankee committed to verifying traceability of twelve molded case circuit breakers installed in class IE systems. Four of the twelve breakers were discussed with Reference (f). Maine Yankee has completed review of the purchasing and audit records for the eight remaining circuit breakers installed in Class IE applications. We have verified that these breakers are traceable to the original manufacturer and records are available on site for NRC review.

This supplement completes Maine Yankee's response to IE Bulletin No. 88-10. We trust this information is satisfactory. Please contact us should you have any questions regarding this matter.

Very truly yours,

MAINE YANKEE

8908160239 890804 PDR ADDCK 05000309

G. D. Whittier, Manager

Nuclear Engineering and Licensing

GDW: BPB

c: Mr. Richard H. Wessman

Mr. William T. Russell Mr. Patrick M. Sears

Mr. Eric J. Leeds

Mr. Cornelius F. Holden

Mr. Donald L. Caphton

04241-SEN-00061