

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

March 6, 1975

CASE EXHIBIT 15

75-05

Texas Utilities Generating Company
ATTN: Mr. Perry G. Brittain
President
2001 Bryan Tower
Dallas, Texas 75201

Docket Nos. 50-445
50-446

Gentlemen:

This refers to the inspection conducted by Messrs. R. C. Stewart and W. G. Hubacek of this office on February 27-28, 1975, of activities authorized by NRC Construction Permit Nos. CPPR-126 and 127 for the Comanche Peak facility, Units 1 and 2, and to the discussion of the findings held by the inspectors with Mr. H. C. Schmidt of your staff at the conclusion of the inspection.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspector.

During the inspection it was found that certain activities under your license appear to be in noncompliance with Appendix B to 10 CFR 50 of the NRC Regulations, "Quality Assurance Criteria for Nuclear Power Plants". The item of noncompliance and references to the pertinent requirements are identified in Section I of the summary of the enclosed report.

We have also examined actions you have taken with regard to the previously identified unresolved item. The status of this item is identified in Section IV of the summary of the enclosed report.



8905040297 890425
PDR FDIA
BAUMAN87-535 PDR

COMANCHE PEAK STEAM ELECTRIC STATION
1980-82 2300 MW INSTALLATION
UNITS 1 & 2
QA/QC MONTHLY REPORT
JANUARY 1975

No changes were made in the B&R QA/QC Department for the month of January. Mr. Byron Kinkade of R. W. Hunt Company reported to work on January 2, 1975. R. W. Hunt is the independent test laboratory which has been contracted to do the concrete testing for the Brown and Root Quality Assurance Department.

No safety related construction activities were started in January. ~~An audit of excavation procedures was conducted because it was possible that excavation work might be redesignated as safety related in later meetings. It was decided that only concrete work on plant site excavation would be considered safety related.~~

~~Qualification and training of site personnel has not~~ commenced and will be scheduled before inspection activities begin.

No Deficiency and Disposition reports have been initiated this month.

~~An AEC audit was conducted by Mr. B. Stewart on January 8 & 9, 1975. Audit results are documented on IM-0106. No major discrepancies were noted.~~ A follow up meeting was held in the ~~USI~~ offices on January 16, 1975.

~~Vendor qualification surveys were performed for admixture suppliers Master Builders and Gifford-Hill. These surveys are documented on letter number IM-0191.~~

INFORMATION COPY

THIS DOCUMENT IS UNCLASSIFIED ONLY.
CONTROL DOCUMENTS ARE FOR
CONTROL PURPOSES AND REVISIONS.