

FC101188-3

**The National
Pharmaceutical
Service Network**

October 11, 1988

John E. Glenn, Ph.D., Chief
Nuclear Materials Safety Section A
Division of Radiation Safety and
Safeguards
U. S. Nuclear Regulatory Commission
Region I
475 Allendale Road
King of Prussia, Pennsylvania 19406

RE: Mail Control Number 109064

Dear Dr. Glenn,

The following information is submitted in order for your continued review of the above referenced license application:

1. The State of Connecticut has indicated that a license number has been issued for this pharmacy, but the final license will not be issued until the pharmacy has been inspected by Connecticut State Board of Pharmacy. Please see attached letter. A copy of the actual license will be sent to your office when it is issued.
2. Syncor confirms that survey meter calibration certificates will be maintained at our Stamford, Connecticut location for at least 2 years after calibration.
3. Syncor confirms that a flow meter device will be placed at all locations for evaluating linear flow through the armports of the glove box.

A base line linear flow will be measured, which shall be consistent with the value used to calculate standard cubic feet per minute semi-annually or quarterly. This linear flow measurement will be obtained at the same position to insure consistency, and will be obtained daily or prior to use of the hood system for handling Iodine-131.

8903140803 8E1112
REG1 LIC30
06-28229-01 PNU

Syncor International Corporation
Health Physics Group
14 Office Park Drive, Suite 300
Little Rock, Arkansas 72211
(501) 221-1126

90:1d 11:100 88.

RECEIVED-REGION 1

109064
OCT 14, 88

OFFICIAL RECORD COPY ML 10


Whatever corrective actions are necessary to return exhaust flow to the required level will be taken in the event that linear flow falls below that quantity necessary for compliance with the commitments stated in the license application.

Examples of Corrective Actions: Replacement of clogged or saturated charcoal filter; Replacement of Inoperable or fatigued fan motor; Repair of crimped or defective ductwork, etc.

Your consideration in this matter is appreciated.

Sincerely,

SYNCOR INTERNATIONAL CORPORATION



Frank M. Comer
Chief Health Physicist, Licensing

FMC/kb

cc: Lou Juliano
Gary Redmore
JoAnn McAnany



STATE OF CONNECTICUT

DEPARTMENT OF CONSUMER PROTECTION

COMMISSION OF PHARMACY

Phone: (203) 566-4832

October 6, 1988

Mr. Louis Juliano, Facility Manager
Syncor International Corp.
Medical Services Group
629 Franklin Ave.
Franklin Square, NY 11010

Dear Mr. Juliano:

Please be informed that the application for Syncor Corp. of
Stamford, CT has been approved and is awaiting final inspection.

The assigned Pharmacy License No. is 1337.

When you are ready for your opening inspection, please notify
this office as soon as possible.

Very truly yours,

A handwritten signature in cursive script, reading "Sharon Milton-Wilhelm".

Sharon Milton-Wilhelm
Board Administrator

SMW:hb