official JUN 2 7 1989 Docket Nos. 50-413, 50-414 License Nos. NPF-35, NPF-52 Duke Power Company ATTN: Mr. H. B. Tucker, Vice President Nuclear Production Department 422 South Church Street Charlotte, NC 28242 Gentlemen: SUBJECT: INSPECTION REPORT NOS. 50-413/89-15 and 50-414/89-15 This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by W. T. Orders and M. S. Lesser on April 30, 1989 to May 27, 1989. The inspection included a review of activities authorized for your Catawba facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report. Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress. The enclosed Inspection Report identifies activities that appeared to violate NRC requirements but are not cited; therefore, no response is required. Your attention is invited to unresolved item identified in the inspection report. This matter will be pursued during future inspections. In accordance with Section 2.790 of the NRC'S "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC's Public Document Room. Should you have any questions concerning this letter, please contact us. M. B. Shymlock/for Alan R. Herdt, Chief Reactor Projects Branch 3 Division of Reactor Projects Enclosure: Inspection Report cc w/encl: (See page 2) 8907070214 890627 PDR ADOCK 05000413

bcc w/encl: NRC Resident Inspector Document Control Desk K. Jabbour, NRR

RII BBonser 6/20/89

MSWyffrock 6/20/89



UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION II 101 MARIETTA ST., N.W. ATLANTA, GEORGIA 30323

Docket Nos. 50-413, 50-414 License Nos. NPF-35, NPF-52 JUN 27 1989

Duke Power Company
ATTN: Mr. H. B. Tucker, Vice President
Nuclear Production Department
422 South Church Street
Charlotte, NC 28242

Gentlemen:

SUBJECT: INSPECTION REPORT NOS. 50-413/89-15 and 50-414/89-15

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by W. T. Orders and M. S. Lesser on April 30, 1989 to May 27, 1989. The inspection included a review of activities authorized for your Catawba facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

The enclosed Inspection Report identifies activities that appeared to violate NRC requirements but are not cited; therefore, no response is required.

Your attention is invited to unresolved item identified in the inspection report. This matter will be pursued during future inspections.

In accordance with Section 2.790 of the NRC'S "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC's Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

Alan R. Herdt, Chief

Reactor Projects Branch 3 Division of Reactor Projects

MB Shymloch

Enclosure: Inspection Report

cc w/enc1: (See page 2)

cc w/encl: T. B. Owen, Station Manager Senior Resident Inspector - McGuire State of South Carolina