

ADMINISTRATIVE CONTROLS

6.3 UNIT STAFF QUALIFICATIONS

6.3.1 Each member of the unit staff shall meet or exceed the minimum qualifications of ANSI/ANS 3.1-1978 except that:

- a. The Radiation Protection Superintendent shall meet or exceed the minimum qualifications of Regulatory Guide 1.8, September 1975.
- b. Personnel in the Health Physics, Chemistry and Radwaste Departments shall meet or exceed the minimum qualifications of ANSI N18.1-1971.
- c. The licensed Operators and Senior Operators shall also meet or exceed the minimum qualifications of the supplemental requirements specified in Sections A and C of Enclosure 1 of the March 28, 1980 NRC letter to all licensees.
- d. Personnel in the Nuclear Quality Assurance Department, and other staff personnel who perform inspection, examination, and testing functions, shall meet or exceed the minimum qualifications of Regulatory Guide 1.58, Rev. 1, September 1980. (Endorses ANSI N45.2.6-1978).

6.4 TRAINING

6.4.1 A retraining and replacement training program for the unit staff shall be maintained under the direction of the Training Manager-Nuclear and shall meet or exceed the requirements and recommendations of Section 5.2 of ANSI 3.1-1978 and Appendix A of 10 CFR Part 55 and the supplemental requirements specified in Sections A and C of Enclosure 1 of the March 28, 1980 NRC letter to all licensees, and shall include familiarization with relevant industry operational experience.

6.5 REVIEW AND AUDIT

6.5.1 PLANT OPERATIONS REVIEW COMMITTEE (PORC)

FUNCTION

6.5.1.1 The PORC shall function to advise the Plant Manager on all matters related to nuclear safety.

COMPOSITION

6.5.1.2 The PORC shall be composed of the following members:

Assistant Plant Manager - Technical Services
Assistant Plant Manager - Operations and Maintenance
Plant Engineering Superintendent
Maintenance Superintendent
Operations Superintendent
Radiation Protection Superintendent
Management Knowledgeable in Quality Assurance/Control

Either of the Assistant Plant Managers will be Chairman and the Plant Engineering Superintendent will be Vice Chairman.

ATTACHMENT B

NPF-38-100

ADMINISTRATIVE CONTROLS

6.3 UNIT STAFF QUALIFICATIONS

6.3.1 Each member of the unit staff shall meet or exceed the minimum qualifications of ANSI/ANS 3.1-1978 except that:

- a. The Radiation Protection Superintendent shall meet or exceed the minimum qualifications of Regulatory Guide 1.8, September 1975.
- b. Personnel in the Health Physics, Chemistry and Radwaste Departments shall meet or exceed the minimum qualifications of ANSI N18.1-1971.
- c. The licensed Operators and Senior Operators shall also meet or exceed the minimum qualifications of 10CFR55. NEW
- d. Personnel in the Nuclear Quality Assurance Department, and other staff personnel who perform inspection, examination, and testing functions, shall meet or exceed the minimum qualifications of Regulatory Guide 1.58, Rev. 1, September 1980. (Endorses ANSI N45.2.6-1978)

6.4 TRAINING

6.4.1 A retraining and replacement training program for the unit staff shall be maintained under the direction of the Training Manager-Nuclear and shall meet or exceed the requirements and recommendations of Section 5.2 of ANSI 3.1-1978 and 10CFR55. NEW

6.5 REVIEW AND AUDIT

6.5.1 PLANT OPERATIONS REVIEW COMMITTEE (PORC)

FUNCTION

6.5.1.1 The PORC shall function to advise the Plant Manager on all matters related to nuclear safety.

COMPOSITION

6.5.1.2 The PORC shall be composed of the:

Chairman:	Assistant Plant Manager (Technical Services or Operations and Maintenance)
Vice Chairman:	Plant Engineering Superintendent
Member:	Maintenance Superintendent
Member:	Operations Superintendent
Member:	Radiation Protection Superintendent
Member:	Management Knowledge in Quality Assurance/Control