

JUL 5 1989

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Donald Shelton
Vice President
Nuclear
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

This refers to the routine safety inspection conducted by Mr. I. T. Yin of this office on June 14-16, 1989, of activities at Davis-Besse Nuclear Power Station authorized by NRC Operating License No. NPF-3 and to the discussion of our findings with Mr. T. J. Myers at the conclusion of the inspection.

The enclosed copy of our inspection report documents our observation of a variety of licensee self-initiated engineering evaluation efforts conducted at the site. Within this area, the inspection consisted of an examination of licensee records and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

ORIGINAL SIGNED BY GEOFFREY C. WRIGHT

G. C. Wright, Chief
Operations Branch

Enclosure: Inspection Report
No. 50-346/89017(DRS)

See Attached Distribution

Yeo
RIII *ly*
Yin/lms
7/5/89

RIII
Yeo
Phillips
7/5/89

405
RIII
RCK for
DeFayette
7/3/89

RIII
Wright
Wright
7/5/89

8907120382 890705
PDR ADDOCK 05000346
Q PNU

PEO

JUL 5 1989

Distribution

cc w/enclosure:

L. Storz, Plant Manager

DCD/DCB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

James W. Harris, State of Ohio

Roger Suppes, Ohio

Department of Health

A. Grandjean, State of Ohio,

Public Utilities Commission

C. J. Haughney, NRR