

D M B

AUG 21 1989

Timken Mercy Medical Center
ATTN: Mr. Jerald Wood, Administrative
Director of Radiology
1320 Timken Mercy Drive, N.W.
Canton, OH 44708

License No. 34-01954-01

30-02694

Gentlemen:

This refers to the routine safety inspection conducted by Mr. S. J. Mulay of this office on July 26, 1989, of activities authorized by NRC Byproduct Material License No. 34-01954-01 and to the discussion of our findings with you and other staff members at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

D. J. Sreniawski, Chief
Nuclear Materials Safety
Section 2

Enclosure: Notice
of Violation

cc w/enclosure:
DCD/DCB (RIDS)

RIII

Mulay/ib

8/17/89

RIII

Sreniawski

8/19/89

8908300162 890821
REG3 LIC30
34-01954-01 PNU

1/1
207