## **OAKLAND INTERNISTS ASSOCIATES**

28625 Northwestern Highway, Suite 200 Southfield, Michigan 48034 Tel. 352-7600

United States Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyr, Illinois 60137

Dear Dr. Adams:

The following communication represents additional information in response to your letter of 7 December, 1988.

A closeout survey was performed by our physicist (James E. Carey, M.S.) on 12/19/88. The survey of our facility at 23077 Greenfield Road consisted of a visual inspection, a survey of ambient exposure levels with an Eberline E-120 with an HP-190 end-window probe (calibrated 10/17/88). Background readings on the survey meter range from .01 to .03 mr/h. No exposure rates above this background was observed at our facility. No sources were found at visual inspection.

A series of swipe tests were performed throughtout our facility (diagram attached\*) and the swipes were counted on a Quantum 8 multichannel analyzer +3" x 3" Nal(Tl) well (calibrated 12/23/88). Background in the measuring window (50-500 keV) was 2384 / 10 minutes on 12/23/88. The swipe counts revealed no statistically significant counts above background.

Our physicist certifies that no byproduct material remains at our Greenfield Road facility and no fixed or removable contamination was measured.

\*o indicates locations where area surveys were performed and + areas where swipes were performed.

Sincerely,

Harold Rodner, M.D. President Oakland Internists Associates

8903170211 890215 REG3 LIC30 21-15642-01 PNU

an 2 gul

JAN 1 9 1989

CONTROL NO. 8 6 7 9 1

Computer Consoler.		Huilwary Elevators	
1 2	OFFICE	A Connera X Connera X + + + + + + + + + + + + + + + + + + +	Нанит
	OFFICE	Radioactive 5 4 3 + 3 + 1 (Lead Lined) "Dose Reporation 1 "Dose Reporation 1 "Dose Reporation 1 addings face hildd) Dose Galibrator Sink Sink Ginelded) Sink Ginelded) Sink Ginelded) Sink Ginelded) Sink Ginelded) Sink Ginelded Backage Reciept Radioactive R	1