

APPENDIX B

U.S. NUCLEAR REGULATORY COMMISSION  
REGION IV

NRC Inspection Report: 50-458/89-30

Operating License: NPF-47

Docket: 50-458

Licensee: Gulf States Utilities (GSU)  
P. O. Box 220  
St. Francisville, Louisiana 70775

Facility Name: River Bend Station (RBS)

Inspection At: RBS, St. Francisville, Louisiana

Inspection Conducted: June 19-23, 1989

Inspector: Dale A. Powers for 8/17/89  
James A. F. Kelly, Senior Security Inspector  
Security and Emergency Preparedness Section Date

Approved: Dale A. Powers 8/17/89  
Dr. Dale A. Powers, Chief, Security and  
Emergency Preparedness Section Date

Inspection Summary

Inspection Conducted June 19-23, 1989 (Report 50-458/89-30)

Areas Inspected: Routine, unannounced inspection of the licensee's physical security program. The areas inspected within the physical security program included management support, security program plans, and audits; protected and vital area (VA) access control of personnel; alarm stations and communications; testing, maintenance, and compensatory measures; and security personnel training and qualifications.

Results: Within the areas inspected, one apparent violation (see paragraph 4.b), one unresolved item (see paragraph 4.c), and no deviations were identified.

As evidenced by the apparent violation involving an inadequate compensatory measure arising from security officer inattentiveness, the licensee needs to strengthen its effort to establish measures to improve personnel performance.

An unresolved item that was identified relates to the adequacy of the security officer firearms qualification certification process. Specifically, the inspector could not ascertain from records which security officer firing attempts were for qualification certification and which were for practice.

8909050043 890821  
PDR ADDCK 05000458  
Q PNU

ENCLOSURE CONTAINS  
SAFEGUARDS INFORMATION  
UPON SEPARATION THIS  
PAGE IS DECONTROLLED