

UNC MINING AND MILLING



Division of United Nuclear Corporation
A **UNC RESOURCES** Company

P.O. Box 3951
Albuquerque, New Mexico 87190


3737 Princeton, NE
Albuquerque, NM 87107

4801 Indian School Road, N.E.
Albuquerque, New Mexico 87110

Telephone 505/265-4424

505/884-1869

April 1, 1981



Gerald W. Stewart
NM Environmental Improvement Division
P. O. Box 968
Santa Fe, NM 87503

Dear Mr. Stewart:

Enclosed for your information and review is a copy of the most recent chemical analysis pertaining to requests in your December 30, 1980 letter.

If you have any questions, please do not hesitate to contact me.

Sincerely,

Thomas M. Hill
Director, Tailings Management

TMH:jb

Enclosures

Science Applications, Inc.


March 27, 1981

Mr. Thomas M. Hill
UNC Mining and Milling
3737 Princeton N.E.
Albuquerque, New Mexico 87109

Dear Tom:

Attached is the latest laboratory analysis received from Core Laboratories for the sampling at Church Rock. It should be forwarded to Gerry Stewart of the EID.

Sincerely,
SCIENCE APPLICATIONS, INC.


Donald G. Silva

DGS:lla
Enclosure

CORE LABORATORIES, INC.
 3428 Stanford Dr., N.E.
 Albuquerque, New Mexico 87107
 Phone: (505) 344-0274

ANALYTICAL REPORT

Client: Science Applications, Inc.
 Address: 505 Marquette, NW, Suite 1200
 Albuquerque, N. M. 87102
 Authorized By: Stuart Faith

Date Received: February 19, 1981
 Analyzed By: JFA
 Date: March 20, 1981
 Job Number: RA-201

Sample Identification	Dissolved Ra 226 (pCi/Liter)	Dissolved Ra 228 (pCi/Liter)	Dissolved Th 230 (pCi/Liter)	Dissolved Pb 210 (pCi/Liter)	Total Th 230 (pCi/Liter)	Total Pb 210 (pCi/Liter)
401 2/18/81	4.6 $\pm$ 0.6	11.7 $\pm$ 6.6	0.00 $\pm$ 3.83	0.00 $\pm$ 1.71	0.00 $\pm$ 2.79	1.27 $\pm$ 2.60