

U. S. NUCLEAR REGULATORY COMMISSION

REGION III

Report No. 50-483/89003(DRSS)

Docket No. 50-483

License No. NPF-30

Licensee: Union Electric Company  
P. O. Box 149-Mail Code 400  
St. Louis, MO 63166

Facility Name: Callaway County Nuclear Power Station, Unit 1

Inspection Conducted: February 13-17, 1989 onsite  
February 22-23, 1989 in NRC Region III office

Type of Inspection: Unannounced Physical Security Inspection

Date of Previous Physical Security Inspection: May 20-27, 1988

Inspector: G. L. Pirtle  
G. L. Pirtle  
Physical Security Inspector

3/21/89  
Date

Approved By: James R. Creed  
James R. Creed, Chief  
Safeguards Section

3/21/89  
Date

Inspection Summary

Inspection on February 13-23, 1989 (Report No. 50-483/89003(DRSS))

Areas Inspected: Included Management Support; Protected and Vital Area Barriers; Access Control - Personnel, Packages, and Vehicles; Alarm Stations and Communications; Power Supply; Testing Maintenance and Compensatory Measures; and Followup on Previous Inspection Findings.

Results: The licensee was found to be in compliance with NRC requirements within the areas examined, except as noted below:

Vital Area Barrier: A vital area access portal was not secured as required by the security plan. The licensee's immediate corrective actions resolved the issue and a written response to the violation was not required.

Five previous open inspection findings were closed. Excessive compensatory measures were employed for a certain segment of the protected area alarm system. Some personnel were requested to be administered another psychological evaluation examination because of unresolved validity issues pertaining to the previously used psychological evaluation test.

8903280231 890321  
PDR ADOCK 05000483  
Q PDC

Enclosure Contains  
SAFEGUARDS INFORMATION  
Upon Separation This  
Page is Decontrolled

The security force personnel were knowledgeable of their duties and responsibilities. The Quality Assurance Department continued to provide aggressive oversight of the security program and security operations were generally well managed.

(DETAILS - UNCLASSIFIED SAFEGUARDS INFORMATION)

Enclosure Contains  
SAFEGUARDS INFORMATION  
Upon Separation This  
Page is Decontrolled