



Vice President  
for Research

(215) 895-2900

March 3, 1989

John D. Kinneman, Chief  
Nuclear Materials Safety Section B  
Division of Radiation Safety and Safeguards  
U.S. Nuclear Regulatory Commission, Region 1  
475 Allendale Road  
King of Prussia, PA 19406

Dear Sir:

Docket No. 030-15139  
Re: Inspection No. 030-15139/89-001  
License No. 37-04594-11

We wish to thank you for your examination and constructive criticism of our Radiation Safety Program. As a result of your inspection visit we have instituted the following corrective measures:

1. All incoming packages of radioactive material are and have been surface monitored with a survey meter. In addition, we are now wipe testing the package with filter paper dampened with a dilute detergent solution. These wipes are then subjected to scintillation counter assay.
2. A meeting of the Radiation Safety Committee has been scheduled and a quarterly calendar will be established at that meeting. (Meeting Date: Monday, March 13, 1989).
3. In order to assure full compliance with our licensing agreement the Radiation Safety Officer will conduct a quarterly review of the conditions of the license, survey operations for compliance and report the status of that compliance as a regular agenda item of the meetings of the Radiation Safety Committee.

Sincerely yours,

Richard Schneider, Ph.D.  
Vice-President for  
Research

RS/JWAB/emb

8903300403 890323  
REG1 LIC30  
37-04594-11 PDC

