RELATED CORRESPONDENCE

DOCKETED

## UNITED STATES OF AMERICA NUCLEAR REGULATORY COMMISSION '89 SEP 12 A10:04

BLFORE THE ATOMIC SAFETY AND LICENSING BOARD

In the Matter of

9161

FLORIDA POWER & LIGHT COMPANY

Docket Nos. 50-250 OLA-4 50-251 OLA-4

(Turkey Point Plant, Units 3 and 4)

## INTERVENORS' RESPONSE TO LICENSEE'S FOLLOW-UP DISCOVERY REQUEST TO THE CENTER FOR NUCLEAR RESPONSIBILITY AND JOETTE LORION

Intervenors, the Center for Nuclear Responsibility and Joette Lorion hereby provide their responses to Licensee's follow-up discovery request:

Response to Interrogatory 1 (a): Intervenors would agree that the NRC Staff has accepted the methods identified in Revision 2 to Regulatory Guide 1.99 as appropriate for determining the adjusted reference temperature (ART) of the materials of reactor vessels in general and the materials of the Turkey Foint reactor vessels in particular. Intervenors are currently researching the issue of whether the use of Revision 2 for the aged Turkey Point reactors is appropriate for determining the ART. Intervenors believe that the use of Revision 2 may not be the most conservative method for calculating the ART for the aged reactor vessels. In addition, Intervenors do not believe the use of Revision 2, part 2 to calculate the ART for Turkey Point Unit 4 is either appropriate or conservative.

8909180081 890908 PDR ADOCK 05000250 PDR PDR Response to Interrogatory 2 (b): At this time, Intervenors are not aware of specific statements or provisions in Revision 2 that are inappropriate. Intervenors believe that it is the Licensee's use of Section 2 of the regulatory guide to predict ART for Unit 4 that is inappropriate. Intervenors believe that Licensee does not meet the criteria for an Integrated Surveillance Program, thus use of the combined Unit 3 and 4 data is not appropriate and not conservative. Intervenors believe that the Unit 4 plant specific surveillance data is the only credible data that can be used to predict ART.and set P/T limits for Unit 4.

Response to Interrogatory 2 (c) : As stated in response to 2 (b) Intervenors do not believe that FPL properly implemented Revision 2 for determination of the ART for Unit 4, because Intervenors do not believe that Turkey Point Units 3 and 4 meet the criteria for an integrated surveillance program, and thus Licensee is underestimating the ART and not being conservative in their setting of the P/T limits for Unit 4. Licensee did not properly implement Revision 2, because they used Section 2 of the guide to calculate ART and set the P/T limits for Unit 4.

Respectfully submitted,

Forthe ton-

Joette Lorion Director, Center for Nuclear Responsibility 7210 Red Road #217 Miami, Fl. 33143 (305) 661-2165

Dated:September 2, 1989

UNITED STATES OF AMERICA · '89 SEP 12 A10:05 NUCLEAR REGULATORY COMMISSION

## BEFORE THE ATOMIC SAFETY AND LICENSING BOARD

In the Matter of	) DOCKL BELVIL
FLORIDA POWER & LIGHT CO.	Docket Nos. 50-250 OLA 50-251 OLA
Turkey Point Plant Units 3 and 4	) (Pressure/Temperature Amendments)

## CERTIFICATE OF SERVICE

I hereby certify that copies of "Intervenors' Responses to Licensee's Foloow-up Discovery Request to the Center for ... Nuclear Responsibility and Joette Lorion" have been served on the following by deposit in the United States Mail, first class, properly stamped and addressed on the date shown below:

Dr. Paul Cotter Atomic Safety & Licensing Board Steel, Hector & Davis U.S. Nuclear Regulatory Commission 4000 SE Financial Center Washington, D.C. 20555

Glenn O. Bright Atomic Safety & Licensing Board Newman & Holtzinger P.C. U.S. Nuclear Regulatory Commission 1615 L. Street NW Washington, D.C. 20555

Jerry Harbour Atomic Safety & Licensing Board U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Office of Secretary U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Janice Moore Office of General Counsel U.S. Nuclear Regulatory Commission WAshington, D.C. 20555

Date: September 8, 1989

John T. Butler Miami, Florida 33131

Steven P. Frantz Suite 1000 Washington, DC 20036

Alte term

Joette Lorion Director, Center for Nuclear Responsibility 7210 Red Road #217 Miami, Florida 33143 (305) 661-2165

\* John Butler was hand delievered a response on September 8, 1989.

STATE OF FLORIDA COUNTY OF DADE

1 4

Before me the undersigned authority, personally appeared JOETTE LORION, who after being duly sworn deposes and says that the foregoing INTERVENORS' RESPONSE TO LICENSEE'S FOLLOW UP DISCOVERY REQUEST TO THE CENTER EOR NUCLEAR RESPONSIBILITY AND JOETTE LORION propounded on the \_\_\_\_\_\_ day of \_\_\_\_\_\_\_ day of \_\_\_\_\_\_\_\_, 1989, are true and correct to the best of her knowledge and ability, and that she has read the RESPONSES and knows the content thereof.

Carnen 3 alayet

Notary Public, State of Florida at Large

MY COMMISSION EXPIRES:

NOTARY PUBLIC STATE OF FLORIDA BY COMMISSION EXP JUNE 13,1991