		AND THE RESIDENCE OF THE PARTY	MENDERHOOF ALDER ALLEGE DAMES AND MANAGES. THE OWNERS	
NRC Form 591			U.S. NUCLEAR RE	GULATORY COMMISSION
10 CFR £.201	SAFETY IN	SPECTION		DINA
1. LICENSEE OF MINNESOMA	применением положения и положения положения положения положения положения положения положения положения положе Дента положения	REGIONAL OFFIC	еменика и портина и Е	and a continuous continuous continuous and an article contain and continuous collaboration of the
DEPT. OF PUBLIC SAFET		U.S. NUCLE	AR REGULATORY C	OMMISSION
DIV, OF EMERGENCY	SLAVELLE	REGION III		
130 HARDMAN ST.	DEWATTED	799 ROOSEV		
SOUTH ST. PAUL, MA	1 55075	GLEN ELLYN	, IL 60137	
3 DOCKET NUMBER(S)	4. LICENSE NUMBER(S)		To DATE OF INSPEC	TION
	77 1/71	1 15	T. 11-	20 1909
030-07209	22-06714	1-02	JUNE !	28,1989
Licensee:	dans ar renovembles and second procuration, und extensive reference and extensive and continue a	COLUMN ECONOMIC PROPERTIES TO THE TOTAL AND	departualities for the content and and the content of the services of the services	
	and used under your linear	on they relate to radius	ation estate and to comp	iance with the Nuclear
The inspection was an examination of the activities of Regulatory Commission's (NRC) rules and regulation	s and the conditions of your	license. The inspection	on consisted of selective e	xaminations of procedures
and representative records, interviews, with personne				
1. Within the scope of this inspection, no violation	ons were observed.			
2. The inspector also verified the steps you have	taken to correct the violation	ns identified during th	ne last inspection. We have	e no further questions on
those actions at this time.	taken to correct the violatio	ne identified during th	io iout mapoorium yra ma	
Sinds Strong Str				
3. During this inspection certain of your activities	es, as checked below, were in	violation of NRC req	uirements.	
THIS IS A NOTICE OF VIOLATION which				
				ted to indicate the presence
of a			. 10 CFR 20.2	03(b), (c), (d), (e) or 34.42.
B Conscious located in				were not properly
B. Containers located in	tive material, 10 CFR 20.20	3(f)(1), or (f)(2).		The state of the s
FXIO LEAK TES	75		of sealed sources were	not performed at the proper
frequencies. 10 CFR		License C	Condition Number	3 (A)
D. Records of				re not properly maintained.
10 CFR	or or	License Condition Nu	ımber	
	the color made available 101	OED 10 11		
E. Documents were not properly posted or of	therwise made available. 10 l	CFR 19.11.		
F. Reports or notifications of	I was the wall		2	ere not made in accordance
with 10 CFR	or	License Condition Nu	ımber	
Will 10 of 11	***************************************			
Пн.				
***************************************				THE REPORT OF THE PARTY OF THE
1				
	***************************************			The lateral Article delicates control resolution by the delication of the party of

I hereby state that within 30 days the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

8907310448 890721 REG3 LIC30 22-06714-02 PD

PDC

SIGNATURE - NRC INSPECTOR