

21 JUL 1989

Docket/License: 50-336/DPR-65

Northeast Nuclear Energy Company
ATTN: Edward J. Mroczka
Senior Vice President - Nuclear
Engineering and Operations Group
P.O. Box 270
Hartford, Connecticut 06101-0270

Gentlemen:

Subject: Millstone 2 Routine Inspection 50-336/89-11 (5/5/89 - 6/15/89)

The enclosed report refers to the above subject inspection. Inspection results were discussed with Mr. Keenan of your staff at the conclusion of the inspection.

As noted in Report Detail 6, events such as changing operating modes with an inoperable emergency diesel generator indicate lapses in operational attention to detail. While this was noted only in relation to minor safety-significant operational requirements, a need for better operational planning is indicated.

Your cooperation with us is appreciated.

Sincerely,

ORIGINAL SIGNED BY

Edward C. Wenzinger, Chief
Projects Branch No. 4
Division of Reactor Projects

Enclosure: NRC Region I Inspection Report 50-336/89-11

cc w/encl:

W. D. Romberg, Vice President, Nuclear Operations
R. M. Kacich, Manager, Generation Facilities Licensing
D. O. Nordquist, Director of Quality Services
S. E. Scace, Station Superintendent
D. B. Miller, Station Superintendent, Haddam Neck
Gerald Garfield, Esquire
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Senior Resident Inspector
State of Connecticut

OFFICIAL RECORD COPY

IR MILL2 89-11 - 0001.0.0
11/29/80

8908020354 890721
PDP ADQCK 05000336
Q PDC

JE01

bcc w/encl:

Region I Docket Room (with concurrences)
Management Assistant, DRMA (w/o enclosures)
DRP Section Chief
J. Shedlosky, SRI, Haddam Neck
G. Vissing, LPM, NRR
R. Bores, DRSS
M. Conner, DRP (Report Detail 3.1)
M. Perkins, DRMA (Report Detail 11.0)
J. Strosneider, DRS (Report Detail 5.1)
T. Rebelowski, DRS (Report Detail 3.1)

RI:DRP

Raymond/meo

7/14/89

19

RI:DRP

McCabe

7/19

RI:DRP

Wenzinger

7/21

OFFICIAL RECORD COPY

IR MILL2 89-11 - 0002.0.0

11/29/80