



Boston Edison

Pilgrim Nuclear Power Station
600 Rocky Hill Road
Plymouth, Massachusetts 02360

L.J. Olivier
Senior Vice President Nuclear

May 29, 1998
BECO Ltr. 2.98. 071

U.S. Nuclear Regulatory Commission
Attn.: Document Control Desk
Washington, D.C. 20555

Docket No. 50-293
License No. DPR-35

The enclosed Licensee Event Report (LER) 98-009-00, "Incorrect Specification Of Seismic Requirements For Safety Relief Valve Line Vacuum Breakers," is submitted in accordance with 10 CFR Part 50.73.

This letter contains the following commitment:

- Determine the seismic capability of the safety relief valve line vacuum breakers and modify, as required, to assure full seismic qualification before startup from RFO #12.

Please do not hesitate to contact me if there are any questions regarding this report.

L. J. Olivier

KRD/JRH/dcg
ler/9800900
Enclosure: LER 98-009-00

IE221

9806080285 980529
PDR ADOCK 05000293
S PDR

cc: Mr. Hubert J. Miller
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Sr. NRC Resident Inspector - Pilgrim Station

INPO Records
700 Galleria Parkway
Atlanta, GA 30339-5957

Standard BECo LER Distribution