



Entergy

Entergy Operations, Inc.
1448 S.R. 333
Russellville, AR 72801
Tel 501 858-5000

June 15, 1998

1CAN069806

U. S. Nuclear Regulatory Commission
Document Control Desk
Mail Station OP1-17
Washington, DC 20555

Subject: Arkansas Nuclear One - Unit 1
Docket No. 50-313
License No. DPR-51
Once Through Steam Generator Inservice Inspection Report

Gentlemen:

Arkansas Nuclear One, Unit 1 (ANO-1), Technical Specification 4.18.6 requires the complete results of each inservice inspection of the once through steam generator (OTSG) tubes to be submitted to the NRC within 45 days of the completion of the inspection. Attached is the Steam Generator Tubing Inservice Inspection Report for the ANO-1 fourteenth refueling outage (1R14). The OTSG tube inspections were completed on April 30, 1998.

The full length tube inspections of both the "A" and "B" OTSGs had Category C-3 results. The attached report supplements the information provided to the NRC by letter dated May 1, 1998 (1CAN059802), which was required to be submitted per ANO-1 Technical Specifications 4.18.6 and 6.12.5 as a result of the C-3 inspection results. The complete results of the inspections are included in the attachment.


Should you have any questions concerning this submittal, please contact me.

200044
9806230238 980615
PDR ADOCK 05000313
G PDR

A0011

U. S. NRC
June 15, 1998
1CAN069806 Page 2

Very truly yours,



Dale E. James
Acting Director, Nuclear Safety

DEJ/jjd
attachment

cc: Mr. Ellis W. Merschoff
Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-8064

NRC Senior Resident Inspector
Arkansas Nuclear One
P.O. Box 310
London, AR 72847

Mr. William D. Reckley
NRR Project Manager Region IV/ANO-1 & 2
U. S. Nuclear Regulatory Commission
NRR Mail Stop 13-H-3
One White Flint North
11555 Rockville Pike
Rockville, MD 20852