



POOR ORIGINAL

TERA APERTURE CARD

30X

- NOTES:
1. CONTROLS ARE MOUNTED ON VENDOR SUPPLIED LOCAL CONTROL PANELS K10, K20, K30, AND K40.
 2. HYDRAZINE SHOULD NOT BE DRAINED TO TURBINE BLDG. SUMP IT SHOULD BE DRAINED TO TURBINE BLDG. SUMP.
 3. LOCAL INDICATOR DLI-4413 IS TO BE LOCKED IN A FILL LINE.

| | | | |
|----------|------|----|------|
| REVISION | DATE | BY | CHKD |
| 1 | | | |
| 2 | | | |
| 3 | | | |
| 4 | | | |
| 5 | | | |
| 6 | | | |
| 7 | | | |
| 8 | | | |

DECTEL
AND INSTRUMENTS

ENCLOSED PLANT INSTRUMENTS
CONSIDERING FORCE OCCUPANCY

PIPING AND INSTRUMENT DIAGRAM
FEEDWATER CHEMICAL ADDITION
UNIT - 2

7220 M-444 B 3

I certify that the image contained on this frame was made in the normal and regular course of business, on the date stated below and that it is an accurate reproduction of the document submitted to reprographics.

This drawing and the design it contains are the property of DECTEL. They are hereby leased and as the lessee's express agreement that they will not be reproduced, copied, loaned, exhibited, or in any way used without the express written consent of the lessor.

RIPS

8112230218

