



POOR ORIGINAL

PRO APERTURE CARD

- NOTES:
1. THESE PIPES SHOULD BE KEPT AS OPEN AS POSSIBLE.
 2. ONE-WAY CONNECTION ON LINE 1" (M-101) MUST BE BETWEEN THE 1" (M-101) AND THE LINE CONNECTION.
 3. ALL EQUIPMENT SHOULD BE SUPPLIED BY THE SOLID WASTE SYSTEM.
 4. BEST AVAILABLE TECHNIQUE INDICATED BY WASTE SHOULD BE LATERAL TIE.
 5. PUMP HEADS IN THESE LINES SHOULD BE PLACED AS CLOSE TO THE PUMP AS POSSIBLE.
 6. ALL PANEL MOUNTED CONTROLS, INDICATORS AND ALARMS ARE LOCATED ON ROOM WALLS UNLESS NOTED.
1. DELETED
 2. DELETED
 3. DELETED
 4. DELETED
 5. DELETED
 6. DELETED
 7. DELETED
 8. DELETED
 9. DELETED
 10. DELETED
 11. CONNECTIONS FOR LINES M-101 AND M-102 SHALL BE AS CLOSE TO THE PUMP AS POSSIBLE. CONNECTION FOR LINE M-103 SHALL BE AS CLOSE TO THE M-103 CONNECTION AS POSSIBLE.
 12. DELETED
 13. DELETED
 14. DELETED
 15. DELETED
 16. DELETED
 17. DELETED
 18. DELETED
 19. THIS TEMPERATURE CRITERIA IS PART OF PUMP PIPING.

NO.	DESCRIPTION	DATE	BY	CHKD.
1	ISSUED FOR CONSTRUCTION			
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				
19				
20				

GENERAL AND APRIL 1982	
ISLAND PLANT UNITS 1 & 2 CONSOLIDATED POWER COMPANY	
PIPING AND INSTRUMENT DIAGRAM SOLID WASTE	
7230	M-425 SH. 2

30X

REVISIONS:

NO.	DESCRIPTION	DATE	BY	CHKD.
1	ISSUED FOR CONSTRUCTION			
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				
19				
20				

RIDS

8302090619

