



HS/110 **

CONTACT	POS	CWD
1 C1 2	1 X	*
0-1-0-1-0	2 X	*
3 C2 4	3 X	*
0-1-0-1-0	4 X	*
1 C1 2	1 X	*
0-1-0-1-0	2 X	*
3 C2 4	3 X	*
0-1-0-1-0	4 X	*
1 C1 2	1 X	*
0-1-0-1-0	2 X	*
3 C2 4	3 X	*
0-1-0-1-0	4 X	*

MAINTAINED CONTACT
* THIS SHEET
** SWITCH CONTACTS SHOULD
MAKE BEFORE BREAK

- NOTES:
1. DE-ENERGIZES ON HI PRESSURIZER LEVEL ERROR SIGNAL. PROVIDES BACKUP STOPPING FOR NORMAL RUNNING & STANDBY CHARGING PUMPS.
 2. DE-ENERGIZES ON LO LEVEL ERROR SIGNAL. PROVIDES BACKUP STARTING FOR NORMAL RUNNING & STANDBY CHARGING PUMPS.
 3. CABLE IS 12 STP #16.

REF:
B-8773-416-113-01 SH 1 (3240-4050)
B-8773-416-113-01 SH 2 (3240-4051)

PRC
APERTURE
CARD

NUCLEAR SAFETY RELATED WPPSS QUALITY CLASS II

EBASCO SERVICES INCORPORATED DIV. CONTROL DR. LVT CH. E. OVALLE DATE SEP 30, 1977		WASHINGTON PUBLIC POWER SUPPLY SYSTEM NUCLEAR PROJECTS NO. 3 & 5 CONTROL WIRING DIAGRAM PRESSURIZER LEVEL CH L-110X, L-110Y SH. I		WPPS-3240 D6001 SHEET 1620
REV. DATE BY APPROVED 7-15-82 9-4-81 9-21-79 11-17-78	VA R M.C. AS	APPROVED <i>M. Wallace</i> L.M. PANELS M.P.S. 143		

17"

11"

8.5"

8.5"

11"

17"

17"

11"

8.5"

8.5"

11"

17"

RIDS

8303170061

