

Hope Creek 2019 SRO Q#80 (Original Question)

Given:

- Pressure transmitter BB-PT-N078A has failed its surveillance calibration check
- The failure is non-conservative

Which one of the following describes the action(s) required by Technical Specifications?

- A. Trip the inoperable channel in one trip system within 12 hours.
- B. Trip the inoperable trip system within one hour and be in at least HOT SHUTDOWN within 12 hours.
- C. Trip the inoperable channel in one trip system within 24 hours.
- D. Commence a normal shutdown within one hour and be in at least Startup within 6 hours, Hot Shutdown with 6 hours and Cold Shutdown within the following 24 hours.

Answer: A