

From: [Linton, Ron](#)
To: [Brad Bingham \(Bbingham@barrick.com\)](#); [Jennifer Ortega \(Jennifer.Ortega@barrick.com\)](#)
Cc: [Reginald Shirley \(regishirley@barrick.com\)](#); [Adam Arguello \(aarguello@barrick.com\)](#); [Alexander, George](#); [Kurt Vollbrecht \(kurt.vollbrecht@state.nm.us\)](#); [Mark Purcell \(purcell.mark@epa.gov\)](#); [Tsosie, Bernadette](#); [Alison Kuhlman \(Alison.Kuhlman@lm.doe.gov\)](#); [Maurer, Anne, NMENV](#); [Winton, Ashlynn, NMENV](#); ["Amber Rheubottom"](#); [Morse, Mike \(CONTR\)](#)
Subject: HMC LTP wells
Date: Wednesday, March 03, 2021 4:42:00 PM

Brad:
The regulatory agencies discussed the Alluvial, Chinle, and tailings wells on the LTP and the map Reggie provided (attached). We agree with the wells HMC has provided in the map to maintain on the site are acceptable for monitoring purposes. Based on the information from Adam Arguello today that Chinle well CF-4 is likely compromised, we suggest replacing CF-4 with both CF-5 and CF-6. Only one of these wells would be needed to add/replace in the NRC licensed monitoring program, but we would suggest maintaining both since they may be the same vintage as CF-4. If either CF-5 or CF-6 is compromised, there would be one Chinle well remaining beneath the LTP, hopefully. Let me know if you have additional questions.

Ron C. Linton, Project Manager
U.S. NRC
phone 301-415-7777
ron.linton@nrc.gov

